

January 24, 2025

Aaron Spooner
SAU 43, Newport Schools
9 Depot Street, Suite 2
Newport, NH 03773

Re: Indoor Air Quality Testing
Richards Elementary School
21 School St, Newport, NH 03773
RPF File 240487

Dear Mr. Spooner,

In accordance with our scope of work dated December 5, 2024, RPF Environmental (RPF) completed indoor air quality (IAQ) testing at the school located at 21 School Street in Newport, NH. As part of this preliminary survey, testing was completed for several common IAQ parameters. The survey was completed on December 30, 2024, by Lauren Williams and Hannah Rivera.


The Richards Elementary School is a multi-story brick structure with classrooms, offices, and common areas for grades Pre-K through 5. RPF was called in to address indoor air concerns by staff. The focus of the survey was Rooms 302, 308, and 315. As part of this preliminary sampling, direct reading instruments were used to test the indoor air quality within the affected areas. Building occupants were not present on the day of the testing.

RESULTS

Carbon Dioxide

Carbon Dioxide (CO₂) gas is found in the atmosphere as a normal constituent at background levels of approximately 350 to 450 parts per million (ppm). CO₂ is also a by-product of human respiration. Typically, in building spaces with inadequate amounts of fresh air introduced and circulated, CO₂ levels and other building and occupant generated air contaminants will accumulate and increase over the course of a day. It is likely that the CO₂ levels will increase in any building space while occupied and fresh outside air is not brought into the space. CO₂ is typically not a problem in and of itself in general indoor environments; however, it is used as an indicator of the adequacy of the fresh air ventilation. CO₂ levels, in general, can be used as an indicator of sufficient ventilation in a space. The primary purpose of introducing fresh tempered outside air into buildings is to dilute the building of occupant generated air contaminants, which would improve the perceived IAQ and occupant comfort and productivity. Inadequate ventilation (and/or elevated temperatures) are frequently causes of complaints, such as respiratory, eye, nose and throat irritation, lethargy, and headaches.

The CO₂ results and testing locations are presented in Appendix A. CO₂ levels at all indoor locations tested were documented in the range of approximately 374 to 424 ppm, which is well below the Occupational Safety and Health Administration Permissible Exposure Limit (OSHA PEL) of 5,000 ppm. These concentration ranges are also below the generally accepted guideline limit of 800 to 1,000 ppm.



The American Society of Heating, Refrigerating and Air Conditioning Engineers (ASHRAE) recommends a guideline in their Standard 62-2001 for Ventilation for Acceptable Indoor Air Quality for a maximum of 700 ppm CO₂ above outside air concentrations as a value under which employee complaints are minimized. On the day of this testing, the outdoor ambient concentration of CO₂ was recorded at 399.5 ppm with a corresponding value of 1,100 ppm, for a maximum CO₂ for perceived acceptable air quality. The ASHRAE standard also calls for a minimum of 20 cubic feet of outside air (FOA) per minute per occupant be introduced into office spaces, and if applicable, 15 cfm per occupant of classrooms, to maintain dilution of contaminants and perceived indoor air quality.

According to the USEPA, pollutant or contaminant source control is usually the most effective way to improve indoor air quality. If source control efforts are not sufficient, increasing the amount of outdoor air coming indoors may prove to be helpful.

Carbon Monoxide


Carbon monoxide (CO) is an odorless, colorless, and toxic gas, and is a by-product of incomplete combustion. Exposure to CO can produce immediate and acute health effects. Transient low levels of CO in building spaces can sometimes be attributed to vehicle exhaust, cigarette smoke, or other sources of combustion in the actual space or adjacent to the air handlers for the space. Minor transient meter readings may also be due to changes in temperature and humidity depending on the test equipment used.

Carbon monoxide concentrations at the tested locations were documented to be less than 1 ppm, which is below the OSHA PEL of 50 ppm. These results and testing locations are presented in Appendix A.

RPF recommends the use of carbon monoxide alarms. Other than proper installation and maintenance of alarms and furnace heating systems, no action is recommended as it relates to CO.

Temperature, Relative Humidity and Dew Point

Temperature, relative humidity and dew point are all interrelated, and all play a role in the interior environment. Measurements were taken for all three on the day of testing and are presented in the following chart with actual testing locations and results included in Appendix A.



Temperature will affect the occupant's perception of IAQ based on employee comfort levels, effect of drafts or airflow, and humidity levels in a building. In most cases, simple adjustments to thermostats and direction of airflow from registers can improve perceived IAQ. As a reference, the temperatures recommended by ASHRAE for general office space ranges from approximately 68° to 75° Fahrenheit in the winter, and from approximately 75° to 80° Fahrenheit in the summer. Temperature readings at all indoor locations tested were documented in the range of 59.4° to 66.8° Fahrenheit.


The amount of water vapor that can be contained in the air varies by the temperature and pressure of the air. The ratio of water vapor in the air to the maximum amount of water vapor the air can hold at a given temperature is expressed as relative humidity (RH). The recommended RH comfort range is 35% to 55%. In general, for buildings, the presence of excessive moisture can lead to mold

growth and other biological contaminants. Low RH, common for buildings in New England during colder months, may contribute to irritated mucous membranes, dry eyes and sinus discomfort while high relative humidity, common in summer, may cause discomfort, as it hinders the body's use of perspiration as a cooling mechanism. RH levels at some indoor locations tested during this survey were below the generally accepted comfort range.

Dew point is related to humidity and is the temperature below which water vapor may start to condense to form water droplets on a surface. If dew forms on interior building materials, the material may become wet, and subsequent fungal growth can occur. For instance, an uninsulated cold-water pipe may form condensation when the temperature of the metal surface is colder than the environmental dew point, and drip onto surfaces causing them to become wet. Dew point measurements on the day of testing ranged from 28° to 42.4° Fahrenheit. Based on these results, the interior temperature readings were all above the Dew Point readings. The results and testing locations are presented in Appendix A.

Volatile Organic Compounds

The scope of this survey included screening for total volatile organic compounds (VOCs). During this testing, total VOCs were measured at 0.07 parts per million (ppm) or less for all locations. These readings are within the "normal indoor air" range depicted below and are comparable to the outside air, which had an average reading of 0.085 ppm. These results are summarized below and presented in Appendix A.



The U.S. Environmental Protection Agency (EPA) reports that levels of volatile organic compounds (VOC) are almost always higher indoors compared to outdoors. Based on past testing, total VOC readings of up to 1 ppm are not atypical in general IAQ settings. In addition, the American Industrial Hygiene Association (AIHA) Technical Committee on Indoor Environmental Quality 1993 publication indicates that a general acceptable range for indoor air total VOC screening is less than 1.0 ppm. EPA studies have also found levels of about a dozen common organic pollutants to be 2 to 5 times higher inside homes than outside, regardless of whether the homes were located in rural or highly industrial areas.

Field experience also suggests the following guide for the use of PID test equipment (RAE Systems by Honeywell) to assess indoor environments:

- <0.1 ppm: normal outdoor air
- 0.1 to 0.4 ppm: normal indoor air
- ≥0.5 ppm: indicates the potential of IAQ contaminants

Individual VOCs can have vastly different standards for acceptable concentrations. Exposure to some specific compounds (such as formaldehyde) can result in health issues for some individuals, at even lower concentrations and levels even exceeding 0.1 ppm. In addition, an individual's odor and irritation responses to organic compounds may be highly variable. Therefore, the total VOC readings must be considered in that light. Further testing can be performed based on the screening results or other factors if you would like additional information on specific VOCs.

Total VOCs include a variety of chemicals that are emitted by a wide array of products used in building construction, maintenance, and consumer materials. Just a few examples of materials that commonly have VOC off-gassing include paints and lacquers, paint strippers, cleaning supplies, pesticides, building materials and furnishings, carpets, upholstery, office equipment such as copiers and printers, correction fluids and carbonless copy paper, graphics and craft materials including glues and adhesives, permanent markers, air fresheners, and photographic solutions. Exposure to VOCs may have short-term and long-term adverse health effects. Studies suggest that the irritant potency of these VOC mixtures can vary.


Total VOC screening does not include specific and individual chemical compound testing for the makeup of the overall VOCs concentrations; and, as with other pollutants, the extent and nature of the health effects will depend on many factors, including level of exposure and length of time exposed. Among the immediate symptoms that some people have experienced soon after exposure to some organics include:

- Eye and respiratory tract irritation
- Headaches
- Dizziness
- Visual disorders and memory impairment

Particulate Matter (PM₁₀)

Particulate matter (PM) is a complex mixture of solid and/or liquid particulates suspended in air. Exposure to inhalable particulates, especially those at 10 microns and smaller, commonly referred to as PM₁₀, are a health concern. Concern of adverse effects to the heart and lungs is well established, especially in children, older adults, and those with existing heart or lung conditions. Outdoor concentrations of PM are of great concern to the EPA, but less is known about the health impacts of indoor PM. Some indoor sources of PM include cooking, combustion activities, some hobbies, outdoor sources introduced indoors, and biological sources.

Direct reading determinations for PM₁₀ at all indoor locations tested were in the range of approximately 3.51 to 24.32 micrograms per cubic meter of air ($\mu\text{g}/\text{m}^3$). The results for half of the interior locations tested were elevated above the values found outside, which was approximately 13.14 $\mu\text{g}/\text{m}^3$. The US EPA does have a National Ambient Air Quality Standard at 150 $\mu\text{g}/\text{m}^3$ which was not exceeded during the testing. The World Health Organization (WHO) also has set a standard of 50 $\mu\text{g}/\text{m}^3$ as a 24-hour average and 25 $\mu\text{g}/\text{m}^3$ as an annual average exposure. These results and testing locations are presented in Appendix A.



These results indicate that the HVAC filters are not reducing the overall particle loading inside the building when compared to the outside air. For a building that implements the use of an HVAC system, it is typical to see a 25% to 35% reduction in total particulates inside a building compared to the outside concentration of particulates while the HVAC units are operational. The feasibility of upgrading the HVAC systems' filter efficiency rating could be investigated if complaints were to be increased at this building.

The American Society of Heating, Refrigeration, and Air Conditioning Engineers (ASHRAE) has recommended filter minimum efficiency reporting value (MERV) of not less than six (6) for filters in HVAC systems supplying air to occupied office space (ASHRAE Standard 62.1-2004-5.9). Follow the manufacturer's recommendations for a filter change out schedule.

Other steps to reduce indoor PM₁₀ concentrations include proper ventilation, away from HVAC intakes, of combustion appliances to the outdoors, proper exhaust vents in cooking areas, proper use of wood stoves, and professional maintenance of heating systems.

Visual Observations for Water Damage and Suspect Fungal Growth

For accessible areas, visual observations for overt signs of water damage and mold growth were completed by RPF during the survey. Water damaged porous building materials which have at any time been wet for 24 to 72 hours should be removed to prevent fungal growth. After addressing and eliminating the source of moisture, materials with water damage/fungal growth should be removed by a qualified professional.

A summary of the visual observations regarding water damage or suspect fungal growth throughout the areas of concern are as follows:

Location	Description
Room 308, closet, above ceiling track	Grey, fuzzy upwards growth

Moisture

Moisture readings were collected on various representative portions of accessible interior building flooring and building components throughout Rooms 302, 308, and 315. The moisture reading results were in the range of approximately <10 percent. Readings of <10 percent moisture can be considered non-detect for moisture content. These results and testing locations are presented below.

Location	Moisture (%)
Room 302, plaster	<10
Room 308, drywall	<10
Room 315, gypsum	<10

Microscopic Screen and Fungal Identification-Surface Swab Sampling

One sample swab was collected from the closet of Room 308. This sample was collected to locate the presence or absence of fungi above the ceiling track. These results and testing locations are presented in Appendix B.


Sample ID	Location	Results
123024 - S01	Room 308, closet, above ceiling track	Trace Ascospores and Cladosporium spores.

Microscopic Screen and Fungal Identification-Airborne Fungal Spores

There are currently no regulatory methods or exposure limits for airborne spores or fungal metabolites for indoor air quality. General guidelines indicate that the indoor and outdoor concentrations should be similar for unaffected buildings. However, elevated concentrations of fungi and their various metabolic by-products can lead to allergic or sensitization reactions, toxic reactions to metabolites, and infections in susceptible populations of people. For those buildings with symptoms, inside airborne concentrations are typically elevated above the outdoor concentrations. In addition, the species documented inside and outside of the structure should be similar and the identification of species found in the indoor air sample(s) and not found in the outdoor air sample(s) would be indicative of the building as a likely source of contamination.

One area air sample each was collected from Rooms 302, 308, 315, and the hallway outside of Room 303. Two area air samples were also collected outside as controls. The requisite analytical field blank was also submitted, for a total of seven (7) area air samples. The concentrations of airborne fungal spores and each testing location are presented below with actual laboratory analysis included in Appendix B of this report.

Sample ID	Location	Results
123024-A01 & 123024-A06	Outside Control Samples	Concentrations of Alternaria, Ascospores, Basidiospores, and Cladosporium
123024-A02	Room 308	Fungal spore concentrations well below the outside controls
123024-A03	Room 302	Fungal spore concentrations well below the outside controls
123024-A04	Hallway outside of room 303	Fungal spore concentrations well below the outside controls
123024-A05	Room 315	Fungal spore concentrations well below the outside controls
123024-B07	Analytical Field Blank	No fungal spores detected



The concentration of total airborne fungal spores in each indoor sample was less than the concentration of total airborne fungal spores in the outdoor control samples. In addition, all individual types of spores detected were consistent with those outside and at lower concentrations than outside. RPF recommends HEPA vacuuming as part of routine maintenance to reduce indoor spores and to reduce dust in general. Many spores are carried indoors from the outdoors where we know spores are present.

Continual inspections for water damaged building materials and fungal growth are recommended as part of routine maintenance. RPF recommends removing water damaged building materials which, at any point, were wet for greater than 24 to 72 hours.

PRELIMINARY OBSERVATIONS AND COMMENTS

In addition to the findings and recommendations provided above, RPF opinions related to the IAQ within the areas of the facility tested based on the results and our observations are presented below.

- Overall, the readings collected inside the building for each IAQ parameter tested during this survey were either within or below their respective standard and/or comfort range, except for RH. Some of the RH levels in the building were below the generally accepted comfort range of 35 to 55%, which is not uncommon during colder months in New England. On the day of the testing. Low RH levels can contribute to irritated mucous membranes, dry eyes and sinus discomfort. The RH levels will naturally increase with the coming warmer weather but, in the meantime, humidifiers can be used to alleviate symptoms. However, it should be noted that if not properly cleaned and maintained, these units can become sources of future fungal growth.

- RPF recommends that building occupants document and track concerns of indoor air quality issues. Occupants should be encouraged to record perceived IAQ discomforts in an effort to track potential concerns and aid in diagnosing future problems. RPF also recommends periodic inspection of areas in and around occupant concern areas throughout the year.
- Heating systems should be inspected on an annual basis or more frequently as required by the manufacturer. RPF recommends implementing and maintaining a preventative maintenance and inspection program for the HVAC system including air filter change-out schedule on a quarterly basis and inspecting for the proper seating of air filters within the filter housing of each air handling unit in order to help eliminate potential air bypass of air filters.
- Ongoing housekeeping and preventative maintenance of the space and building envelope should continue.
- Looking at the airborne fungal spore samples collected in the building, the total fungal spore concentrations of each of these samples were below the concentration present in the outside control. Comparing the fungal species to the outside control samples, the samples collected inside the building had similar fungal species and concentrations well below outside side controls.
- Visible fungal growth, if identified in the future, should be removed by qualified personnel using appropriate methods in accordance with current industry standards and guidelines. Although no visible indicators of moisture intrusion were observed at the time of the RPF testing, all sources of water or moisture incursion onto building materials must be addressed, controlled and/or rectified or fungal growth will occur. Work plan development and post remediation verification by a third-party industrial hygiene firm, independent from the remediation contractor, is also recommended as standard of care. Regardless of the level of effort expended to remediate fungal growth, the potential for fungal growth to return exists if the building materials were to become wet again or be subject to elevated humidity levels.
- Prior to any demolition or renovation of building materials, the areas of impact must be inspected for the presence of asbestos by a qualified asbestos inspector pursuant to various state and federal regulations. This inspection should also address other items that could be impacted by work resulting in contamination or health risks, including but not limited to lead paint, mercury containing products, and other common hazardous building materials.

If you have any questions or require additional information on any sample results or recommendations, please feel free to contact our office. Thank you for utilizing the services of RPF for this important project.

Sincerely,

RPF Environmental, Inc.



Krystalle S. Diaz, CMI
EH&S Technician

Enclosures: Appendix A: Testing Results
 Appendix B: Laboratory Results
 Appendix C: Example Picture
 Appendix D: General Fungal Descriptions
 Appendix E: Limitations and Methodologies

240487 Richards Elementary School, IAQ Rpt

APPENDIX A

TABLE 1
Preliminary IAQ Testing

Client: Sau 43, Newport Schools		Site Address: Richards School - 21 School St, Newport, NH 03773				Date Samples Collected: 12/30/2024		
Location / Room	Time	TVOC (ppm)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Temp (°F)	Relative Humidity (%)	Dew Point (°F)	PM10 (ug/m ³)
Outside	0802	0.12	399	<0.1	55.4	47.3	35.5	3.64
Room 308	0822	0.07	424	<0.1	59.4	52.6	42.4	20.48
Room 302	0848	0.06	395	<0.1	66.8	31.4	35.6	13.55
Hallway, Outside room 303	0900	0.07	415	<0.1	64.9	33.9	35.9	24.32
	0903	0.05	398	<0.1	64.1	35.2	36.1	12.06
3rd floor, Attic stairs	0913	0.05	414	<0.1	62.3	36.9	35.7	9.01
Attic, South	0915	0.05	408	<0.1	61.3	28.1	28.0	3.51
Room 315	0919	0.06	374	<0.1	62.6	44.2	40.6	18.40
Stairwell B	0924	0.06	400	<0.1	64.2	41.7	40.4	8.23
Outside	0942	0.05	400	<0.1	58.9	47.0	38.4	22.64
ACGIH TLV	-	-	5,000	25	-	-	-	-
OSHA PEL	-	-	5,000	50	-	-	-	-
ASHRAE recommended	-	-	1,100	2.5	-	35-55	-	-
EPA Reference Level Indicator	-	-	1,000	9	-	-	-	150

ppm – parts per million in air; ppb – parts per billion in air

OSHA PEL – Occupational Safety and Health Administration Permissible Exposure Limit for eight-hour time weighted average (8hr-TWA).

ACGIH TLV – American Conference of Governmental Industrial Hygienist Threshold Limit Value for eight-hour time weighted average (8hr-TWA).

ASHRAE – American Society of Heating, Refrigeration and Air Conditioning Engineers, 62-2001 standard.

EPA – Environmental Protection Agency.

Gray Wolf IAQ monitor has a sensitivity of +/- 1 ppm for carbon monoxide and +/- 0.01 ppm for volatile organic compounds.

Results of less than 1 ppm carbon monoxide or 0.01 ppm volatile organic compounds can be considered "non-detect".

Gray Wolf Dust meter senses particles of less than 10 microns diameter.

APPENDIX B

Direct Exam: Swab Analysis

SAI Method B-SOP-005



Customer: RPF Environmental Inc.
320 1st NH Turnpike
Northwood, NH 03261

Project: 240487-SAU43 Newport IAQ

Attn: Sean Smith
Lauren Williams

Lab Order ID:	10071793
Analysis:	DES
Date Received:	12/31/2024
Date Reported:	01/03/2025

[illegible]

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AIIHA EMPAT program for fungi. EMPAT Laboratory ID: 173190. Reporting Limit equals Analytical Sensitivity. Analytical Sensitivity equals 1 spore or structure.

LEGEND: 1=Trace (1-10 Spores); 2=Light (11-100 spores); 3=Abundant (101-300); 4=Loaded (>300 spores)

Darrin Parrick (1)

Analyst

B-F-015 r17 2/28/2027

Scientific Analytical Institute, Inc. 4604 Dundas Dr. Greensboro, NC 27407 (336) 292-3888

Approved Signatory



Lab Use Only
Lab Order ID: 10071793
Client Code:

Company: RPF Environmental	Contact: Sean Smith
Address: 320 1st NH Turnpike	Phone ☐ : 603-942-5432
Northwood, NH 03261	Fax ☐ : 603-942-5300
	Email ☒ : SeanS@airpf.com

Billing/Invoice Information	Turn Around Times	
Company: RPF Environmental	90 Min. ☐	48 Hours ☐
Contact: Katie Betts-Levine	3 Hours ☐	72 Hours ☒
Address: 320 1st NH Turnpike	6 Hours ☐	96 Hours ☐
Northwood, NH 03261	12 Hours ☐	120 Hours ☐
	24 Hours ☐	144 ⁺ Hours ☐

PO Number:

Project Name/Number: 240487- SAU43 Newport IAQ

Spore Trap - Slit Impact, ie, AOC/Allergenco (STA)	☐
Spore Trap Other, ie. Micro-5 (STO)	☐
Direct Exam Tape (DET)	☐
Direct Exam Swab (DES)	☒
Direct Exam Bulk (DEB)	☐
Fungal Culture Air (FCA)	☐
Fungal Culture Swab (FCS)	☐
Fungal Culture Bulk (FCB)	☐
Bacteria Culture Air (BCA)	☐
Bacteria Culture Bulk (BCB)	☐
Bacteria Culture Swab (BCS)	☐
Biolog (BLG)	☐
Drinking Water (BCC) (Coliform/E.coli)	☐
Other:	☐

[illegible]

Total # of Samples 1

Relinquished by	Date/Time	Received by	Date/Time
Laven Williams	12/30/24	CS	12/31/24 1030AM



SAI Method B-SOP-003

Project: 240487 - SAU43 Newport IAQ

Sample ID	123024-A01	123024-A02	123024-A03	EXTERIOR		
Lab Sample ID	10071795_0001	10071795_0002	10071795_0003	AVERAGE		
Description	Outside	Room 308	Room 302			
Lab Notes						
Volume (L)	150	150	150			
Analytical Sensitivity (counts/m³)	39	39	39			
IDENTIFICATION	Raw Count	Concentration (counts/m³)	% Of Total	Raw Count	Concentration (counts/m²)	% Of Total
<i>Alleraria</i>	1	39.2	1.08%			
Ascomspores	61	2390	65.69%	7	274	63.6%
Basidiospores	29	1140	31.2%	3	118	27.3%
<i>Cladosporium</i>	2	78.4	2.15%	1	39.2	9.09%

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAT. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AHA EMPAT[®] program for fungi. EMPAT Laboratory ID: 173190. Reporting Limit equals Analytical Sensitivity. Unless indicated, areas and volumes were provided by the customer.

Darrin Parrick (7)

Analyst

Approved Signatory

B-F-028 r15 5/27/2025

Scientific Analytical Institute, Inc. 4604 Dundas Dr. Greensboro, NC 27407 (336) 292-3888

Page 1 of 3



SAI Method B-SOP-003

Project: 240487 - SAU43 Newport IAQ

Sample ID	123024-A04	123024-A05	123024-A06	EXTERIOR		
Lab Sample ID	10071795_0004	10071795_0005	10071795_0006	AVERAGE		
Description	Hallway outside of room 303	Room 315	Outside	N/A		
Lab Notes				N/A		
Volume (L)	150	150	150	N/A		
Analytical Sensitivity (counts/m³)	39	39	39	N/A		
IDENTIFICATION	Raw Count	Concentration (counts/m³)	% Of Total	Raw Count	Concentration (counts/m²)	% Of Total
<i>Alternaria</i>	1	39.2	33.3%	1	39.2	0.840%
Ascospores	1	39.2	33.3%	2	78.4	66.7%
<i>Cladosporium</i>	1	39.2	33.3%			

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AITFA EMPAT program for lung. EMPAT Laboratory ID: 173190. Reporting Limit equals Analytical Sensitivity. Unless indicated, areas and volumes were provided by the customer.

Page 2 of 3

Paul Hines

Approved Signatory

**SAI Method B-SOP-003**

Customer: RPF Environmental Inc.
320 1st NH Turnpike
Northwood, NH 03261

Attn: Sean Smith
Lauren Williams

Lab Order ID: 10071795**Analysis:** STA

Date Received: 12/31/2024

Date Reported: 01/03/2025

Project: 240487 - SAU43 Newport IAQ

[illegible]

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. Unless otherwise noted blank sample correction was not performed on analytical results. Scientific Analytical Institute participates in the AIHA EMPAT program for fungal analysis. The report number is 173190. Reporting Limit equals Analytical Sensitivity. Unless indicated, areas and volumes were provided by the customer.

Darrin Patrick (7)

Analyst

Scientific Analytical Institute, Inc. 4604 Dundas Dr. Greensboro, NC 27407 (336) 292-3888

B-F-028 r15 5/27/2025

Page 3 of 3

Edward A. Tines


APPENDIX C




1. Richards Elementary School



2. Room 308



3. Room 308, closet ceiling



4. Room 308, closet ceiling track



5. Room 302



6. Room 315

PICTURES

Site Address:
21 School St, Newport NH 03773

RPF Environmental
TESTING & CONSULTING SERVICES

www.airpf.com
888-SAFE AIR

File No. 240487

APPENDIX D

Regulatory standards for the testing for and exposure limits for airborne mold, and fungal spores have not been established. The presence of fungi and mold is common in many environments with over 1,000 fairly common species of mold, many we are routinely in contact with are not hazardous under normal conditions.

Alternaria

Alternaria is a large and widespread genus, the conidia of which are easily carried by the wind, with peak concentrations in the summer and early fall. *Alternaria* is commonly found in house dust, carpets, textiles, on horizontal surfaces in building interiors, and window frames. It is one of the main fungal causes of allergy, being a common type I & III allergen. Outdoors, it may be isolated from samples of soil, seeds and plants, and is frequently reported in air. The large spore size suggests that this fungus will deposit in the nose, mouth and upper respiratory tract causing nasal septum infections. It has also been associated with hypersensitivity pneumonitis. It is a common cause of extrinsic asthma. Acute symptoms include edema and bronchospasms; chronic cases may develop pulmonary emphysema. Baker's asthma is associated with inhalation of *Alternaria* conidia present in flour. Other diseases caused by *Alternaria* include: Farmer's lung, mycotic keratitis, skin infections, and osteomyelitis. Also, the species *A. alternata* is capable of producing tenuazonic acid and other toxic metabolites that may be associated with disease in humans or animals. Several species are pathogenic to plants and contribute to the spoilage of agricultural products. *Alternaria* has been isolated from substrates such as sewage, leather, stone monuments, optical instruments, cosmetics, computer disks, and jet fuel

Ascospore

Ascospores are a general category of spores that have been produced by means of sexual reproduction (in a sack-like structure called an ascus). These are ubiquitous saprobes and plant pathogens, many of which are easily identifiable (i.e. *Chaetomium*). This group contains potential opportunistic pathogens, toxin producers, and allergens depending on the genus and species. A rupture in the top portion of the ascus disperses the spores during rain or in times of high humidity. Some asexual fungi, such as *Aspergillus* and *Penicillium* can become sexual under specific conditions, these are then considered ascomycetes and are given distinct names. The presence of these spores normally is associated with indoor air infiltration.

Basidiospore

Basidiospores are a general category of sexual spores that have been released from the basidium of a fungus. A ubiquitous type I & III allergen, saprobe and plant pathogen, mainly found in gardens, forests, and woodlands. Spores disseminate during rain or in times of high humidity. Rarely opportunistic pathogens, Basidiospores may produce toxins, including amanitins, monomethyl-hydrazine, muscarine, ibotenic acid, and psilocybin. Basidiospores are an agent of dry wood rot, which may destroy the structure wood of buildings.

Cladosporium

Cladosporium is widely distributed in air and rotten organic material. *C. herbarum* is the most frequently found species in outdoor air in temperate climates. It is often found indoors, usually in lesser numbers than outdoors. The dry conidia become easily airborne and are transported over long distances. This fungus is often encountered in dirty refrigerators, especially in reservoirs where condensation is collected. It can easily be seen on moist window frames covering the whole painted area with a velvety olive-green layer. *Cladosporium* often discolors interior paint, paper, or textiles stored under humid conditions. Houses with poor ventilation, houses with

APPENDIX E

LIMITATIONS

1. The observations and conclusions presented in the Report were based solely upon the services described herein, and not on scientific tasks or procedures beyond the RPF Environmental, Inc. Scope of Work (SOW) as discussed in the proposal and/or agreement. The conclusions and recommendations are based on visual observations and testing, limited as indicated in the Report, and were arrived at in accordance with generally accepted standards of industrial hygiene practice and asbestos professionals. The nature of this survey or monitoring service was limited as indicated herein and in the report or letter of findings. Further testing, survey, and analysis is required to provide more definitive results and findings.
2. For site survey work, observations were made of the designated accessible areas of the site as indicated in the Report. While it was the intent of RPF to conduct a survey to the degree indicated, it is important to note that not all suspect ACM material in the designated areas were specifically assessed and visibility was limited, as indicated, due to the presence of furnishings, equipment, solid walls and solid or suspended ceilings throughout the facility and/or other site conditions. Asbestos or hazardous material may have been used and may be present in areas where detection and assessment is difficult until renovation and/or demolition proceeds. Access and observations relating to electrical and mechanical systems within the building were restricted or not feasible to prevent damage to the systems and minimize safety hazards to the survey team.
3. Although assumptions may have been stated regarding the potential presence of inaccessible or concealed asbestos and other hazardous material, full inspection findings for all asbestos and other hazardous material requires the use of full destructive survey methods to identify possible inaccessible suspect material and this level of survey was not included in the SOW for this project. For preliminary survey work, sampling and analysis as applicable was limited and a full survey throughout the site was not performed. Only the specific areas and /or materials indicated in the report were included in the SOW. This inspection did not include a full hazard assessment survey, full testing or bulk material, or testing to determine current dust concentrations of asbestos in and around the building. Inspection results should not be used for compliance with current EPA and State asbestos in renovation/demolition requirements unless specifically stated as intended for this use in the RPF report and considering the limitations as stated therein and within this limitations document.
4. Where access to portions of the surveyed area was unavailable or limited, RPF renders no opinion of the condition and assessment of these areas. The survey results only apply to areas specifically accessed by RPF during the survey. Interiors of mechanical equipment and other building or process equipment may also have asbestos and other hazardous material present and were not included in this inspection. For renovation and demolition work, further inspection by qualified personnel will be required during the course of construction activity to identify suspect material not previously documented at the site or in this survey report. Bordering properties were not investigated and comprehensive file review and research was not performed.
5. For lead in paint, observations were made of the designated accessible areas of the site as indicated in the Report. Limited testing may have been performed to the extent indicated in the text of the report. In order to conduct thorough hazard assessments for lead exposures, representative surface dust testing, air monitoring and other related testing throughout the building, should be completed. This type of in depth testing and analysis was beyond the scope of services for the initial inspection. For lead surveys with XRF readings, it is recommended that surfaces found to have LBP or trace amount of lead detected with readings of less than 4 mg/cm² be confirmed using laboratory analysis if more definitive results are required. Substrate corrections involving destructive sampling or damage to existing surfaces (to minimize XRF read-through) were not completed. In some instances, destructive testing may be required for more accurate results. In addition, depending on the specific thickness of the paint films on different areas of a building component, differing amounts of wear, and other factors, XRF readings can vary slightly, even on the same building component. Unless otherwise specifically stated in the scope of services and final report, lead testing performed is not intended to comply with other state and federal regulations pertaining to childhood lead poisoning regulations.

6. Air testing is to be considered a “snap shot” of conditions present on the day of the survey with the understanding that conditions may differ at other times or dates or operational conditions for the facility. Results are also limited based on the specific analytical methods utilized. For phase contrast microscopy (PCM) total airborne fiber testing, more sensitive asbestos-specific analysis using transmission electron microscopy (TEM) can be performed upon request.
7. For asbestos bulk and dust testing, although polarize light microscopy (PLM) is the method currently recognized in State and federal regulations for asbestos identification in bulk samples, some industry studies have found that PLM may not be sensitive enough to detect all of the asbestos fibers in certain nonfriable material, vermiculate type insulation, soils, surface dust, and other materials requiring more sensitive analysis to identify possible asbestos fibers. In the event that more definitive results are requested, RPF recommends that confirmation testing be completed using TEM methods or other analytical methods as may be applicable to the material. Detection of possible asbestos fibers may be made more difficult by the presence of other non-asbestos fibrous components such as cellulose, fiber glass, etc., by binder/matrix materials which may mask or obscure fibrous components, and/or by exposure to conditions capable of altering or transforming asbestos. PLM can show significant bias leading to false negatives and false positives for certain types of materials. PLM is limited by the visibility of the asbestos fibers. In some samples the fibers may be reduced to a diameter so small or masked by coatings to such an extent that they cannot be reliably observed or identified using PLM.
8. For hazardous building material inspection or survey work, RPF followed applicable industry standards; however, RPF does not warrant or certify that all asbestos or other hazardous materials in or on the building has been identified and included in this report. Various assumptions and limitations of the methods can result in missed materials or misidentification of materials due to several factors including but not limited to: inaccessible space due to physical or safety constraints, space that is difficult to reach to fully inspect, assumptions regarding the determination of homogenous groups of suspect material, assumptions regarding attempts to conduct representative sampling, and potential for varying mixtures and layers of material sampled not being representative of all areas of similar material.
9. Full assessments often requires multiple rounds of sampling over a period of time for air, bulk material, surface dust and water. Such comprehensive testing was beyond the scope of RPF services. In addition clearance testing for abatement, as applicable, was based on the visual observations and limited ambient area air testing as indicated in the report and in accordance with applicable state and federal regulations. The potential exists that microscopic surface dust remains with contaminant present even in the event that the clearance testing meets the state and federal requirements. Likewise for building surveys, visual observations are not sufficient alone to detect possible contaminant in settled dust. Unless otherwise specifically indicated in the report, surface dust testing was not included in the scope of the RPF services.
10. For abatement or remediation monitoring services: RPF is not responsible for observations and test for specific periods of work that RPF did not perform full shift monitoring of construction, abatement or remediation activity. In the event that problems occurred or concerns arouse regarding contamination, safety or health hazards during periods RPF was not onsite, RPF is not responsible to provide documentation or assurances regarding conditions, safety, air testing results and other compliance issues. RPF may have provided recommendations to the Client, as needed, pertaining to the Client’s Contractor compliance with the technical specifications, schedules, and other project related issues as agreed and based on results of RPF monitoring work. However, actual enforcement, or waiving of, contract provisions and requirements as well as regulatory liabilities shall be the responsibility of Client and Client’s Contractor(s). Off-site abatement activities, such as waste transportation and disposal, were not monitored or inspected by RPF.
11. For services limited to clearance testing following abatement or remediation work by other parties: The testing was limited to clearance testing only and as indicated in the report and a site assessment for possible environmental health and safety hazards was not performed as part of the scope of this testing. Client, or Client’s abatement contractor as applicable, was responsible for performing visual inspections

of the work area to determine completeness of work prior to air clearance testing by RPF.

12. For site work, including but not limited to air clearance testing services, in which RPF did not provide full site safety and health oversight, abatement design, full shift monitoring of all site activity, RPF expresses no warranties, guarantees or certifications of the abatement work conducted by the Client or other employers at the job site(s), conditions during the work, or regulatory compliance, with the exception of the specific airborne concentrations as indicated by the air clearance test performed by RPF during the conditions present for the clearance testing. Unless otherwise specifically noted in the RPF Report, visual inspections and air clearance testing results apply only to the specific work area and conditions present during the testing. RPF did not perform visual inspections of surfaces not accessible in the work area due to the presence of containment barriers or other obstructions. In these instances, some contamination may be present following RPF clearance testing and such contamination may be exposed during and after removal of the containment barriers or other obstructions following RPF testing services. Client or Client's Contractor is responsible for using appropriate care and inspection to identify potential hazards and to remediate such hazards as necessary to ensure compliance and a safe environment.
13. The survey was limited to the material and/or areas as specifically designated in the report and a site assessment for other possible environmental health and safety hazards or subsurface pollution was not performed as part of the scope of this site inspection. Typically, hazardous building materials such as asbestos, lead paint, PCBs, mercury, refrigerants, hydraulic fluids and other hazardous product and materials may be present in buildings. The survey performed by RPF only addresses the specific items as indicated in the Report.
14. For mold and moisture survey services, RPF services did not include design or remediation of moisture intrusion. Some level of mold will remain at the site regardless of RPF testing and Contractor or Client cleaning efforts. RPF testing associated with mold remediation and assessments is limited and may or may not be representative of other surfaces and locations at the site. Mold growth will occur if moisture intrusion deficiencies have not been fully remedied and if the site or work areas are not maintained in a sufficiently dry state. Porous surfaces in mold contaminated areas which are not removed and disposed of will likely result in future spore release, allergen sources, or mold contamination.
15. Existing reports, drawings, and analytical results provided by the Client to RPF, as applicable, were not verified and, as such, RPF has relied upon the data provided as indicated, and has not conducted an independent evaluation of the reliability of these data.
16. Where sample analyses were conducted by an outside laboratory, RPF has relied upon the data provided, and has not conducted an independent evaluation of the reliability of this data.
17. All hazard communication and notification requirements, as required by U.S. OSHA regulation 29 CFR Part 1926, 29 CFR Part 1910, and other applicable rules and regulations, by and between the Client, general contractors, subcontractors, building occupants, employees and other affected persons were the responsibility of the Client and are not part of the RPF SOW.
18. The applicability of the observations and recommendations presented in this report to other portions of the site was not determined. Many accidents, injuries and exposures and environmental conditions are a result of individual employee/employer actions and behaviors, which will vary from day to day, and with operations being conducted. Changes to the site and work conditions that occur subsequent to the RPF inspection may result in conditions which differ from those present during the survey and presented in the findings of the report.

METHODOLOGY

The results of the air quality testing are representative of the conditions present on the day of the testing and should be considered a snap shot of conditions within the facility. Additional rounds of testing may be required to obtain a statistically valid set of data representative of a variety of conditions which may be present within the facility.

Each of the methods used is discussed separately below.

(GRAYWOLF) Carbon Dioxide, Carbon Monoxide, Relative Humidity, Temperature, Dew Point, and Volatile Organic Compounds

Direct reading determinations for carbon dioxide (CO₂), carbon monoxide (CO), relative humidity (RH), temperature (T), dew point, and total volatile organic compounds (VOCs) were completed using a Greywolf Indoor Air Quality Monitor. The Greywolf was calibrated for CO₂ and CO with a span gas of known concentration prior to the start of the testing program.

Airborne Particulates

Direct reading determinations for airborne particulates at the size range of 10 microns and lower were measured using a Greywolf Handheld 3016-IAQ Airborne Particulate Meter. Thirty second samples were collected at each sampling location.

Moisture

A Tramex moisture encounter plus, which enables a non-invasive moisture measurement and detection in a wide range of building materials, was used to conduct direct reading determinations for approximate moisture content in accessible building materials. The instrument operates on the principle that the electrical impedance of a material varies in proportion to its moisture content. The instrument measures the electrical impedance of the sample by creating a low frequency alternating electric field between the electrodes. This field penetrates the material under test to a depth of approximately 1 ¼ inches. The Tramex meter was zero checked, dry reading verified and field checked prior to the start of the testing program.

Microscopic Screen and Fungal Identification-Surface Swab Sampling

Surface swab sampling of representative surfaces where suspect mold growth was observed and was completed using surface swabs. A sterile swab was wetted with buffer solution and wiped over the surface of the affected areas and immediately placed in its proper handling container, sealed with tape for shipping and labeled. The RPF Industrial Hygienist performed the swab sampling using separate sets of latex gloves on his hands or washed hands with isopropyl gel prior to each sample to reduce the potential for cross contamination.

At the completion of the sampling, the samples were sealed, labeled and shipped on blue ice under chain of custody to Scientific Analytical Institute (SAI) of Greensboro, NC for analysis. SAI is accredited by the AIHA for analysis of microbiological samples. The method will detect many but not all fungi present on the limited surface which was tested.

Microscopic Screen and Fungal Identification-Airborne Fungal Spores

Sampling for airborne fungal spores was completed using a hi-volume air-sampling pump calibrated at a rate of approximately 15 liters of air per minute (lpm) using Zefon Air-O-Cell spore trap cassettes. All samples were collected at approximately three to five feet above the ground for a period of ten minutes per cassette per location. The Air-O-Cell cassette sampling and analysis method provides for the identification and quantification of many, but not all, genus of fungal spores that may be present in the air on the day of the testing and does not determine the viability of fungi spores but rather a total count of spores, both viable and non-viable. At the completion of the sampling, the samples were sealed, labeled, and shipped under chain of custody to EMSL Analytical or Scientific Analytical Institute (SAI) of Greensboro, NC for microscopic analysis. This method will detect many but not all fungal spores present in the air on the day of the testing. EMSL or SAI is accredited by the AIHA for analysis of microbiological samples. Additional rounds of testing may be required to fully document fungal ecology due to high variability of spore concentrations.