On Nov. 20 at approximately noon, the United States Army will detonate degraded lead azide ($Pb(N_3)_2$) at the Iowa Army Ammunition Plant located at 17571 DMC Highway 79, Middletown, IA 52638. This detonation has been planned in coordination with the U.S. Environmental Protection Agency under the Resource Conservation and Recovery Act. In-place detonation by Explosive Ordnance Disposal experts is the safest way to eliminate the explosive safety hazard. The degraded lead azide has been deemed unsafe for relocation.

Extensive modeling efforts predict that the potential level of lead particles in the air may be elevated. The detonation will result in an air plume with some lead-containing particles which will disperse in the air and deposit on the ground. Lead is toxic to humans and animals. The goal of this advisory is to provide the public with actionable information out of an abundance of caution to minimize lead exposure. There are two primary pathways of concern:

1. Lead exposure by breathing in air after the detonation.
2. Lead exposure from dust on surfaces.


The US Army will release two maps; one for airborne exposure to lead dust through respiration, and one for exposure from lead dust on surfaces. The potential airborne exposure map is current as of today, but it will change prior to the detonation due to weather forecast changes. The maps will be updated at this website: https://www.army.mil/asc#org-iowa-army-ammunition-plant. Members of the public should check for updates to these maps:

- 48 hours in advance of the detonation.
- 6 hours in advance of the detonation and every hour thereafter until the detonation.
- After the event, the US Army will issue a final estimate of the impacted area.

To minimize potential exposure, members of the public who live or work in the affected areas should consider taking the following actions on the day of the detonation:

- Consider avoiding the affected area.
- If you are inside of the affected areas, avoid outdoor air by staying indoors.
- Keep windows and doors closed.
- If it is safe to do so, set heating and cooling systems to “recirculate” to minimize outdoor air exposure and maximize indoor air filtration until the plume passes by your community.
- Avoid unnecessary travel through impacted areas.
- After the US Army determines the air exposure period has ended, consider cleaning indoor and outdoor surfaces such as play surfaces for children and windowsills.

- If your car was parked outside, consider washing your car at a car wash to minimize your contact with potentially exposed surfaces.
- Learn more about actions you can take to protect you and your family from potential exposures to lead at https://www.epa.gov/lead/actions-reduce-potential-lead-exposure and https://www.epa.gov/lead/learn-about-lead.



PUBLIC ADVISORY

POTENTIAL EXPOSURE TO TOXIC LEAD DUST


LEAD AIR DISPERSION

Consider avoiding the highlighted area or remain indoors with windows/doors closed

Children under six are especially vulnerable to Lead exposure

AWAIT US ARMY TO ANNOUNCE ALL-CLEAR DETERMINATION

Issued Nov. 15, 2026



Deposition of lead-containing dust may occur after the detonation on surfaces within certain areas affected by the detonation plume,

All humans, but especially children, pregnant individuals, older adults, and other sensitive populations should avoid outdoor activities within affected areas.

All members of the public who reside or work within this affected area should:

- Remain indoors during the potential exposure period if they cannot evacuate beforehand;
- Close all windows, exterior doors, and other openings during the exposure period;
- Turn off or place heating, ventilation, and air conditioning (HVAC) systems in recirculation mode, minimize outdoor air intake, and maximize indoor air filtration during the potential exposure period; and
- Avoid travelling through the affected area during the potential exposure period.
- Wet-clean surfaces that may be contacted by children, including outdoor play

equipment, toys, tables and chairs, handrails, patios, decks, exterior windowsills, and other high-contact surfaces. Such instructions should include specific cleaning and dust mitigation procedures to address deposited and airborne lead particles which minimizes overall human exposure to lead.

Media Advisory:

Middletown, Iowa -- Two controlled detonations are scheduled at Iowa Army Ammunition Plant on Nov. 20 at approximately noon. Residents will be asked to vacate the area from 8 a.m. to 2 p.m. local time, and dust is expected to linger for no more than one hour, depending on wind speed. This is a planned and controlled safety operation to dispose of the degraded lead azide and has been permitted by the U.S. Environmental Protection Agency under the Resource Conservation and Recovery Act.While safety measures will be fully enforced, the controlled detonation will cause temporary noise, ground vibrations, and a dust plume that will contain some lead. Residents in Middletown will hear a loud noise; feel vibrations from two consecutive, rapid detonations; and will see a plume of dust. Due to the potential for localized window damage, the U.S. Army recommends that residents in the Middletown City Park neighborhood temporarily vacate the area during the detonations out of an abundance of caution. Residents are asked to vacate starting at 8 a.m. when the explosives team begins setting up the detonations. If residents need a place to stay, they are invited to come to the Armed Forces Reserve Center at 16815 DMC HWY 34 Middletown, IA 52638. All family members are welcome, including pets. Please ensure pets are appropriately secure in carrying containers or on leashes. Refreshments will be available at this relatively new building, complete with a gym and classrooms. It is the same location as the open house the Army hosted on the detonation. The U.S. Army has taken extraordinary measures to mitigate the plume by following strict permit requirements set by the EPA such as earthworks, soil wetting, and air sampling. Pre-controlled detonation sampling has taken place; air monitors have been established for perimeter air monitoring during the event; and environmental sampling of the blast radius will take place. MEDIA ADVISORY: You are invited to go to the Armed Forces Reserve Center at 116815 DMC HWY 34 Middletown, IA 52638 to view the detonation.

Point of Contact:

Justine Barati
Public Affairs Specialist
Army Sustainment Command
Office Phone: 520-693-1317
Work Cell: 309-206-3461