



Gantner- Floor drain for fireline, Floor repoured




Gantner- Fireline Tie in




Gantner-Second Floor Block Work



Gilbert- Windows Installation



Gilbert- Ceiling Grid Installation




Gilbert- Block Fill in Hallway



Gilbert- Tape and Spackle



Gantner- Second Floor Patition Walls



Gantner- New Workflow Fencing Installed




Gantner- Brick and Roofing Material Onsite




Gantner-Sprinkler Room Exterior Wall Completed




Gantner- Curtain Wall Being Framed




Gilbert- Windows being Framed in



Gilbert- Corner Beads Spackled



Gilbert- Removal of transition floor so new subfloor can be poured



16th- Openings cut for Ductwork



Gantner- Roofing Being Installed




Gantner- Curtain Wall Completed




Gantner-Scissor Lift onsitefor Roof Access




Gantner- New Divit in Parking Lot after Rain



Gilbert- Interior Doors OnSite




16th- Ceiling Grids and Lighting Installed



16th- Grading around the site



Gilbert- Sidewalks Striped




Gilbert- Walls Primed




Gilbert- Man Trap




16th- Entry way Graded, Stairs removed



Gantner- Gantner 2nd Floor Temp Power on



Gantner- Stairwell Temp Lighting



Gantner-Second Floor Carriers Installed for Bathroom



Gantner- Electrical Rough Continues