RADON GAS SAMPLING AND ANALYSIS REPORT

Prepared by:

For:

Jeff Webster
Warrensburg (MO) R6 School District
201 S. Holden Street
Warrensburg, MO 64093

Project:

Radon Gas Sampling and Analysis
Warrensburg High School
1411 S. Ridgeview Drive
Warrensburg, MO 64093

TES Project No.: 26086ALMR.04

May 19, 2026

Full Service Environmental Consulting, Testing & Contracting
2418 Merriam Lane, KCK 66106 | Phone: 913-432-5500 | www.titankc.com

May 19, 2026 TES Project No.: 26086ALMR.04

Jeff Webster
Warrensburg (MO) R6 School District
201 S. Holden Street
Warrensburg, MO 64093

RE: Report of Findings for Radon Gas Sampling and Analysis
Warrensburg High School
1411 S. Ridgeview Drive
Warrensburg, MO 64093

Dear Client:

Titan Environmental Services, Inc. (TES) is pleased to provide this report of findings associated with the radon gas testing performed at 1411 S. Ridgeview Drive, Warrensburg, MO 64093 The radon gas testing was performed by Karla Granger, a National Radon Proficiency Program (NRPP) Radon Measurement Technician (Certificate #: 107404-RMP, Expiration date: January 31, 2028). Testing was conducted in accordance with HUD Guidelines and in general accordance with ANSI/AARST MA-MFLB-2023: Protocol for Conducting Radon and Radon Decay Product Measurements in Multifamily, School, Commercial and Multi-Use Buildings. The purpose of the testing was to establish baseline data for the presence of radon at the property.

Background Information

Radon gas comes from the natural (albeit radioactive) breakdown of uranium in soil, rock, and water, and enters the body through inhalation. Radon content within the air is ubiquitous; it can be found within any home in the United States, in both indoor and outdoor air. As such, it can be found in the air content of any building, regardless of property history or use.

Radon is the second-leading cause of lung cancer in the United States, behind tobacco use. Radon gas decays into radioactive particles which are trapped within the alveoli of the lungs when inhaled. As they break down further, these particles release small bursts of energy. This can damage lung tissues and lead to lung cancer of the course of your lifetime. Not everyone exposed to elevated levels of radon will develop lung cancer; factors that may affect your risk of lung cancer can include factors such as time exposed, other chemicals the lungs are exposed to (e.g. tobacco smoke, Volatile Organic Compounds (VOCs), etc.), and other such factors.

Radon Testing Procedure

On May 11, 2026, TES placed **one hundred and fifty (150)** radon gas measurement devices throughout the subject property, excluding blank samples.

Duplicates are pairs of detectors or monitors deployed in the same location, side-by-side, for the same measurement period. The purpose of duplicates is to evaluate precision or agreement between detectors or monitors. Some variation between detectors of monitors. Some variation between the results of each detector is expected, but excessive variation could result from poor quality sampling media. Blanks help evaluate any detector response from sources other than radon exposure (i.e., in the manufacturing process, during shipment, storage, analysis, and handling. Ten percent (10%) duplicates and five percent (5%) field blanks were deployed for quality assurance and control (QA/QC) purposes. Each sample was set for a minimum of 48 hours in a location that was between 2.5 and 5.5 feet off the floor. This area is chosen due to it being the height at which air is typically inhaled by most human beings.

On May 13, 2026, TES Collected the Pro-Chek radon measurement devices and submitted the samples to Air-Chek Inc., in Mills River, NC (NRPP Certified Lab no.: 101138AL). The test and analysis was performed to comply with the US Environmental Protection Agency (USEPA) and State of Missouri Department of Health and Senior Services (MDHSS) short-term radon testing protocol. The test results represent the average radon concentration at the time of the sampling event, and at each specific location tested within the subject property.

There is a level of uncertainty with any measurement result, due to statistical variations and other factors. These include factors such as daily and seasonal variations in radon concentrations, weather, operation of the dwelling, or possible interference with the necessary test conditions. The average radon gas level at the time of sampling, measured in picocuries of radon per liter of air (pCi/L: +/- 0.3) has been included as well. With the exception of six missing devices (were not present upon retrieval), no tampering was observed during the course of the sampling event. Closed building conditions were observed for the duration of the test.

The following table details the results of the radon sampling event at the subject property:

Sample #	Location	EPA Recommended Action Guideline	Test Results
7556230	Class 209	4.0 pCi/L	<0.3 pCi/L
7556231	Class 210	4.0 pCi/L	<0.3 pCi/L
7556235	Class 210 (Dup)	4.0 pCi/L	0.6 pCi/L
Average for Class 210		4.0 pCi/L	0.5 pCi/L
7556236	Class 208	4.0 pCi/L	0.5 pCi/L
7556237	Class 207	4.0 pCi/L	<0.3 pCi/L
7556232	Class 205	4.0 pCi/L	<0.3 pCi/L
7556238	Class 203	4.0 pCi/L	<0.3 pCi/L
7556233	Class 206	4.0 pCi/L	0.6 pCi/L
7556234	Class 204	4.0 pCi/L	1.0 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
7556241	Class 202	4.0 pCi/L	1.0 pCi/L
7556243	Break Room	4.0 pCi/L	0.8 pCi/L
7556244	Commons by Shop	4.0 pCi/L	0.7 pCi/L
7556239	Commons by Shop (Dup)	4.0 pCi/L	1.0 pCi/L
Average for Commons by Shop		4.0 pCi/L	0.9 pCi/L
7556242	Commons SE Corner	4.0 pCi/L	0.9 pCi/L
7556240	Commons West Corner	4.0 pCi/L	0.7 pCi/L
7556249	Class 137	4.0 pCi/L	1.2 pCi/L
7556250	Class 139	4.0 pCi/L	1.2 pCi/L
7556251	Class 101	4.0 pCi/L	1.1 pCi/L
7556259	Class 94	4.0 pCi/L	0.6 pCi/L
7556252	Class 101 B	4.0 pCi/L	0.9 pCi/L
7556253	94A	4.0 pCi/L	0.8 pCi/L
7556245	Class 92	4.0 pCi/L	0.7 pCi/L
7556246	Class 93	4.0 pCi/L	0.8 pCi/L
7556260	Class 91	4.0 pCi/L	0.6 pCi/L
7556254	Class 95	4.0 pCi/L	Missing Upon Retrieval
7556261	Little Theatre	4.0 pCi/L	0.7 pCi/L
7556257	Class 100	4.0 pCi/L	1.0 pCi/L
7556258	Class 80	4.0 pCi/L	<0.3 pCi/L
7556255	Class 81	4.0 pCi/L	<0.3 pCi/L
7556263	Class 82	4.0 pCi/L	<0.3 pCi/L
7556264	Class 82 (Dup)	4.0 pCi/L	0.7 pCi/L
Average for Class 82		4.0 pCi/L	0.5 pCi/L
7556265	Class 402	4.0 pCi/L	0.9 pCi/L
7556267	Class 403	4.0 pCi/L	0.9 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
7556266	Class 403 (Dup)	4.0 pCi/L	0.7 pCi/L
Average for Class 403		4.0 pCi/L	0.8 pCi/L
7556268	Class 404	4.0 pCi/L	<0.3 pCi/L
7556262	Class 406	4.0 pCi/L	0.7 pCi/L
7556273	Class 405	4.0 pCi/L	0.8 pCi/L
7556271	400's Hallway	4.0 pCi/L	0.7 pCi/L
7556274	Class 303	4.0 pCi/L	<0.3 pCi/L
7556272	300's Hallway	4.0 pCi/L	0.6 pCi/L
7556269	200's Hallway	4.0 pCi/L	0.5 pCi/L
7556275	Aux Gym	4.0 pCi/L	0.6 pCi/L
7556277	Library B Room	4.0 pCi/L	1.4 pCi/L
7556270	Library Table Area	4.0 pCi/L	0.7 pCi/L
7556278	Library Table Area (Dup)	4.0 pCi/L	1.0 pCi/L
Average for Library Table Area		4.0 pCi/L	0.9 pCi/L
7556280	L20	4.0 pCi/L	1.0 pCi/L
7556256	Library	4.0 pCi/L	0.8 pCi/L
7556279	Class 105	4.0 pCi/L	1.1 pCi/L
7556276	Library "Lion Room"	4.0 pCi/L	1.1 pCi/L
7556281	Class 107	4.0 pCi/L	1.1 pCi/L
7556283	Class 112	4.0 pCi/L	0.9 pCi/L
7556284	Class 112 "Office"	4.0 pCi/L	1.0 pCi/L
7556282	Class 110	4.0 pCi/L	0.7 pCi/L
7556287	Class 108	4.0 pCi/L	0.7 pCi/L
7556285	Class 106	4.0 pCi/L	0.8 pCi/L
7556288	Class 102	4.0 pCi/L	0.9 pCi/L
7556289	Class 102 (Dup)	4.0 pCi/L	1.0 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
Average for Class 102		4.0 pCi/L	1.0 pCi/L
7556291	Aux Gym (Dup)	4.0 pCi/L	0.6 pCi/L
7556286	Aux Gym	4.0 pCi/L	<0.3 pCi/L
Average for Aux Gym		4.0 pCi/L	0.5 pCi/L
7556295	Aux Gym	4.0 pCi/L	Missing Upon Retrieval
7556290	Aux Gym “Coach’s Office”	4.0 pCi/L	0.9 pCi/L
7556292	Aux Gym	4.0 pCi/L	0.6 pCi/L
7556297	Commons	4.0 pCi/L	0.6 pCi/L
7556302	Lecture Room	4.0 pCi/L	0.8 pCi/L
7556296	Lecture Room	4.0 pCi/L	0.8 pCi/L
7556299	Lecture Room (Dup)	4.0 pCi/L	0.6 pCi/L
Average for Lecture Room		4.0 pCi/L	0.7 pCi/L
7556300	Dressing Room	4.0 pCi/L	0.7 pCi/L
7556248	Big Gym	4.0 pCi/L	1.0 pCi/L
7556301	Big Gym (Dup)	4.0 pCi/L	<0.3 pCi/L
Average for Big Gym		4.0 pCi/L	0.7 pCi/L
7556298	Big Gym	4.0 pCi/L	Missing Upon Retrieval
7556303	A-3	4.0 pCi/L	<0.3 pCi/L
7556294	Office A” Left”	4.0 pCi/L	<0.3 pCi/L
7556304	Office B “Right”	4.0 pCi/L	<0.3 pCi/L
7556403	Percussion	4.0 pCi/L	1.5 pCi/L
7556402	Big Gym	4.0 pCi/L	1.1 pCi/L
7556401	Big Gym	4.0 pCi/L	1.3 pCi/L
7556293	A1	4.0 pCi/L	0.5 pCi/L
7556247	A1 Dup	4.0 pCi/L	<0.3 pCi/L
Average for A1		4.0 pCi/L	0.4 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
7556337	Attendance Office	4.0 pCi/L	0.6 pCi/L
7556334	Main Office	4.0 pCi/L	0.8 pCi/L
7556338	Principal	4.0 pCi/L	<0.3 pCi/L
7556333	04 “Safe” Storage Room	4.0 pCi/L	0.5 pCi/L
7556330	Workroom	4.0 pCi/L	0.7 pCi/L
7556332	Activities Director	4.0 pCi/L	<0.3 pCi/L
7556339	Assistant Principal	4.0 pCi/L	0.6 pCi/L
7556340	Process Coordinator	4.0 pCi/L	0.6 pCi/L
7556345	Assistant Principal	4.0 pCi/L	0.9 pCi/L
7556346	Assistant Principal	4.0 pCi/L	0.7 pCi/L
7556347	90-Bandroom	4.0 pCi/L	0.8 pCi/L
7556351	90-Bandroom (Dup.)	4.0 pCi/L	0.8 pCi/L
Average for 90-Bandroom		4.0 pCi/L	0.8 pCi/L
7556352	Office C-Nurses Station	4.0 pCi/L	0.7 pCi/L
7556348	Office A-Counselors	4.0 pCi/L	0.6 pCi/L
7556353	Office B-Social Worker	4.0 pCi/L	0.5 pCi/L
7556354	Office G-Glenn	4.0 pCi/L	0.6 pCi/L
7556355	Office F-Nimmo	4.0 pCi/L	0.7 pCi/L
7556356	Office E-Bentley	4.0 pCi/L	0.6 pCi/L
7556357	Class 301	4.0 pCi/L	<0.3 pCi/L
7556358	Class 303	4.0 pCi/L	<0.3 pCi/L
7556359	Class 305	4.0 pCi/L	0.5 pCi/L
7556360	Class 304	4.0 pCi/L	<0.3 pCi/L
7556363	Class 306	4.0 pCi/L	<0.3 pCi/L
7556361	Class 308	4.0 pCi/L	<0.3 pCi/L
7556362	Class 308 (Dup)	4.0 pCi/L	0.7 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
Average for Class 308		4.0 pCi/L	0.5 pCi/L
7556364	Class 307	4.0 pCi/L	<0.3 pCi/L
7556366	Class 310	4.0 pCi/L	<0.3 pCi/L
7556371	Class 309	4.0 pCi/L	<0.3 pCi/L
7556365	Class 135	4.0 pCi/L	1.0 pCi/L
7556367	Class 133 A	4.0 pCi/L	1.1 pCi/L
7556368	Class 133 B	4.0 pCi/L	0.9 pCi/L
7556370	Class 134	4.0 pCi/L	1.1 pCi/L
7556369	Class 132	4.0 pCi/L	1.1 pCi/L
7556373	Class 130	4.0 pCi/L	1.0 pCi/L
7556372	Class 130 (Dup)	4.0 pCi/L	1.0 pCi/L
Average for Class 130		4.0 pCi/L	1.0 pCi/L
7556374	Class 129	4.0 pCi/L	1.1 pCi/L
7556375	Class 127	4.0 pCi/L	0.9 pCi/L
7556379	Class 126	4.0 pCi/L	0.6 pCi/L
7556381	Class 124	4.0 pCi/L	1.0 pCi/L
7556382	Woodshop	4.0 pCi/L	1.0 pCi/L
7556376	Workshop A Office	4.0 pCi/L	1.1 pCi/L
7556377	Class 122	4.0 pCi/L	1.0 pCi/L
7556378	Class 122 A	4.0 pCi/L	0.8 pCi/L
7556380	Class 120	4.0 pCi/L	1.0 pCi/L
7556383	Class 121	4.0 pCi/L	1.0 pCi/L
7556384	Class 119	4.0 pCi/L	0.9 pCi/L
7556385	Class 119 (Dup)	4.0 pCi/L	0.8 pCi/L
Average for Class 119		4.0 pCi/L	0.9 pCi/L
7556386	Class 118	4.0 pCi/L	0.9 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
7556387	Class 115	4.0 pCi/L	0.9 pCi/L
7556388	Class 116	4.0 pCi/L	1.3 pCi/L
7556389	Class 114	4.0 pCi/L	1.1 pCi/L
7556390	Class 113	4.0 pCi/L	0.8 pCi/L
7556391	90 Office	4.0 pCi/L	1.0 pCi/L
7556395	Weight Room	4.0 pCi/L	0.9 pCi/L
7556396	Aerobics Room	4.0 pCi/L	0.6 pCi/L
7556392	Class 83	4.0 pCi/L	1.8 pCi/L
7556393	Class 83 (Dup)	4.0 pCi/L	1.8 pCi/L
Average for Class 83		4.0 pCi/L	1.8 pCi/L
7556397	Office	4.0 pCi/L	2.9 pCi/L
7556394	Music Library	4.0 pCi/L	1.9 pCi/L
7556398	Guard Closet	4.0 pCi/L	1.4 pCi/L
7556399	Mud Room	4.0 pCi/L	1.8 pCi/L
7556400	Practice Room	4.0 pCi/L	1.5 pCi/L
7556404	A2	4.0 pCi/L	<0.3 pCi/L
7556323	104	4.0 pCi/L	Missing Upon Retrieval
7556324	100’s Hallway	4.0 pCi/L	Missing Upon Retrieval
7556321	100’s Hallway	4.0 pCi/L	Missing Upon Retrieval
7556309	100’s Hallway	4.0 pCi/L	<0.3 pCi/L
7556307	Fitness Hallway	4.0 pCi/L	<0.3 pCi/L
7556316	Room 12	4.0 pCi/L	<0.3 pCi/L
7556306	Break Room/Copy Room	4.0 pCi/L	<0.3 pCi/L
7556315	Process Coordinator	4.0 pCi/L	<0.3 pCi/L
7556308	Spirit Store	4.0 pCi/L	<0.3 pCi/L
7556349	A13 (LB)	4.0 pCi/L	<0.3 pCi/L

Sample #	Location	EPA Recommended Action Guideline	Test Results
7556341	A13 (LB)	4.0 pCi/L	<0.3 pCi/L
7556336	A13 (LB)	4.0 pCi/L	<0.3 pCi/L
7556331	A14 (OB)	4.0 pCi/L	<0.3 pCi/L
7556350	A14 (OB)	4.0 pCi/L	<0.3 pCi/L
7556343	A14 (OB)	4.0 pCi/L	<0.3 pCi/L
7556342	A15 (FB)	4.0 pCi/L	<0.3 pCi/L
7556335	A15 (FB)	4.0 pCi/L	<0.3 pCi/L
7556344	A15 (FB)	4.0 pCi/L	<0.3 pCi/L
Average Radon Concentration Complex-Wide		4.0 pCi/L	0.9 pCi/L

Based on the results of the samples collected from the site, all samples collected reported radon gas concentrations were below the USEPA action guideline of 4.0 pCi/L at the time of our sampling. As radon concentrations were observed to be well below the USEPA action level of 4.0 pCi/L, no mitigation procedures are thus recommended to be implemented at this time. Test results of 0.5 pCi/L or less are, for all practical purposes, equivalent to the radon levels found in fresh air.

However, six devices were missing upon retrieval **(Classroom 95, Aux Gym, Big Gym, 104, and two in the 100's Hallway)**. The recommendation under national testing standards is to retest any areas where radon devices were missing or lost, regardless of whether all other completed tests came back below the EPA Action Level of 4.0 pCi/L. Because radon levels are highly localized and can vary significantly from room to room based on structural differences, floor cracks, and air movement, one cannot assume a missing area is safe just because adjacent rooms were below the EPA Action Level.

The OSHA radon exposure limit is an average concentration for 40 hours in any workweek of 7 consecutive days. The still applicable 1971 radon-222 exposure limit for adult employees is $1 * 10^{-7}$ microcuries per milliliter (μ Ci/ml), or 100 pCi/L averaged over a 40-hour workweek. The average concentration in outdoor air is 0.4 p/Ci/L or 10% of the USEPA's 4 pCi/L action level. The average radon concentration in the indoor air during this assessment is 0.9 pCi/L; below both the national EPA average for indoor air in homes (1.3 pCi/L); and the EPA Action Level. The average indoor radon levels of Johnson County, Missouri, as determined by Federal EPA Radon Concentration data (and confirmed by data by Air Chek, Inc.) is 2.4 pCi/L (between 2.0 pCi/L and the USEPA action level of 4.0 pCi/L).

Recommendations:

Because there were several devices missing during this assessment, the client has the option of conducting another short-term test; preferably in the same season as the initial test. Under strict ANSI/AARST MA-MFLB standards, large building testing requires a specific percentage of ground-contact rooms to be evaluated. A missing device drops the valid statistical sample size. Those specific rooms **must be retested** to achieve compliance and secure clear certification.

Retest all building(s) at least every 5 years, and in conjunction with any sale of the building. Furthermore, it is recommended that subsequent tests be performed in a different season as the initial test, to obtain at least one test under a different season that represents a significant portion of the yearlong operating condition for the building (e.g. if the initial test was performed in summer, consider performing the next test in winter, and so on). In addition, be certain to retest the property whenever any of the following circumstances occur:

- A new addition is constructed or alterations for building reconfiguration or rehabilitation occur.
- A ground-contact area not previously tested is occupied.
- Heating or cooling systems are altered in such a way that air distribution or pressure relationships change within the property.
- Ventilation is altered by extensive weatherization, changes to mechanical systems, or comparable procedures.
- Sizeable openings to soil occur due to any of the following:
    - Groundwater or slab surface water control systems are added or altered (e.g., sumps, perimeter drain tile, shower/tub retrofits, etc.)
    - Natural settlement occurs, causing major cracks to develop.
    - Earthquakes, construction blasting, or formation of sinkholes occur near the subject property.
    - A radon mitigation system is altered, modified, or repaired.
- If renovations or other structural changes are planned in the lower level of the subject property.


Additional information regarding radon testing and mitigation can be accessed at www.epa.gov/radon and https://health.mo.gov/living/environment/radon.

Closing Comments

TES has performed the tasks set forth above in a thorough and professional manner consistent with industry standards. This limited scope radon sampling event and report does not and cannot address correction of the conditions that caused the contamination to occur nor does this report reflect on conditions post-cleanup that may develop that could support or encourage the redevelopment of the asbestos contamination. Furthermore, TES cannot guarantee and does not warrant that these limited testing events have revealed all asbestos contamination affecting the site. The results reported and any opinions reached by TES are for the benefit of the client. The results and opinions set forth by TES in its report will be valid as of the date of the report.

TES appreciates the opportunity to be of service to you. If you have any questions, please do not hesitate to contact us.

Respectfully,



Karla Granger
NRPP Radon Measurement Professional

Appendices: Appendix A – Radon Gas Analytical Testing Data
Appendix B – USEPA & State of Missouri Radon Zone Maps
Appendix C – Site Photographs & Drawings
Appendix D – TES Personnel Certifications

APPENDIX A – RADON GAS ANALYTICAL TESTING DATA

A Full Service Environmental Consulting and Testing Firm
Phone: 913-432-5500 Fax: 913-432-0704

RADON SAMPLE CUSTODY FORM

CLIENT: Warrensburg (MO) R6 School District **PROJECT No: 26086ALMR.04**
JOB LOCATION: Warrensburg High School, 1411 S. Ridgeview Dr., Warrensburg, MO 64093
CONTACT/PHONE: Karla Granger 913-432-5500

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556230	Class 209	5/11/26	4:00 PM	5/13/26	4:06 PM
7556231	Class 210	5/11/26	4:02 PM	5/13/26	4:08 PM
7556235	Class 210 (Dup)	5/11/26	4:02 PM	5/13/26	4:08 PM
7556236	Class 208	5/11/26	4:04 PM	5/13/26	4:10 PM
7556237	Class 207	5/11/26	4:05 PM	5/13/26	4:11 PM
7556232	Class 205	5/11/26	4:07 PM	5/13/26	4:13 PM
7556238	Class 203	5/11/26	4:10 PM	5/13/26	4:15 PM
7556233	Class 206	5/11/26	4:13 PM	5/13/26	4:17 PM
7556234	Class 204	5/11/26	4:16 PM	5/13/26	4:20 PM
7556241	Class 202	5/11/26	4:20 PM	5/13/26	4:23 PM
7556243	Break Room	5/11/26	4:28 PM	5/13/26	4:32 PM
7556244	Commons by Shop	5/11/26	4:37 PM	5/13/26	4:41 PM
7556239	Commons by Shop (Dup)	5/11/26	4:37 PM	5/13/26	4:41 PM
7556242	Commons SE Corner	5/11/26	4:42 PM	5/13/26	4:44 PM
7556240	Commons West Corner	5/11/26	4:46 PM	5/13/26	4:47 PM
7556249	Class 137	5/11/26	4:50 PM	5/13/26	4:51 PM
7556250	Class 139	5/11/26	4:52 PM	5/13/26	4:54 PM
7556251	Class 101	5/11/26	4:55 PM	5/13/26	4:57 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556259	Class 94	5/11/26	4:58 PM	5/13/26	5:01 PM
7556252	Class 101 B	5/11/26	5:01 PM	5/13/26	5:08 PM
7556253	94A	5/11/26	5:06 PM	5/13/26	5:13 PM
7556245	Class 92	5/11/26	5:10 PM	5/13/26	5:18 PM
7556246	Class 93	5/11/26	5:14 PM	5/13/26	5:21 PM
7556260	Class 91	5/11/26	5:17 PM	5/13/26	5:25 PM
7556254	Class 95	5/11/26	5:20 PM	5/13/26	Missing
7556261	Little Theatre	5/11/26	5:31 PM	5/13/26	5:37 PM
7556257	Class 100	5/11/26	5:39 PM	5/13/26	5:42 PM
7556258	Class 80	5/11/26	5:47 PM	5/13/26	5:50 PM
7556255	Class 81	5/11/26	5:51 PM	5/13/26	5:52 PM
7556263	Class 82	5/11/26	5:55 PM	5/13/26	5:58 PM
7556264	Class 82 (Dup)	5/11/26	5:55 PM	5/13/26	5:58 PM
7556265	Class 402	5/11/26	6:00 PM	5/13/26	6:02 PM
7556267	Class 403	5/11/26	6:04 PM	5/13/26	6:08 PM
7556266	Class 403 (Dup)	5/11/26	6:04 PM	5/13/26	6:08 PM
7556268	Class 404	5/11/26	6:08 PM	5/13/26	6:12 PM
7556262	Class 406	5/11/26	6:12 PM	5/13/26	6:17 PM
7556273	Class 405	5/11/26	6:16 PM	5/13/26	6:22 PM
7556271	400’s Hallway	5/11/26	6:22 PM	5/13/26	6:28 PM
7556274	Class 303	5/11/26	6:33 PM	5/13/26	6:38 PM
7556272	300’s Hallway	5/11/26	6:39 PM	5/13/26	6:43 PM
7556269	200’s Hallway	5/11/26	6:45 PM	5/13/26	6:50 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556275	Aux Gym	5/11/26	6:52 PM	5/13/26	6:56 PM
7556277	Library B Room	5/11/26	6:57 PM	5/13/26	7:00 PM
7556270	Library Table Area	5/11/26	7:02 PM	5/13/26	7:05 PM
7556278	Library Table Area (Dup)	5/11/26	7:02 PM	5/13/26	7:05 PM
7556280	L20	5/11/26	7:05 PM	5/13/26	7:07 PM
7556256	Library	5/11/26	7:07 PM	5/13/26	7:10 PM
7556279	Class 105	5/11/26	7:10 PM	5/13/26	7:14 PM
7556276	Library “Lion Room”	5/11/26	7:13 PM	5/13/26	7:17 PM
7556281	Class 107	5/11/26	7:15 PM	5/13/26	7:21 PM
7556283	Class 112	5/11/26	7:22 PM	5/13/26	7:25 PM
7556284	Class 112 “Office”	5/11/26	7:22 PM	5/13/26	7:26 PM
7556282	Class 110	5/11/26	7:28 PM	5/13/26	7:30 PM
7556287	Class 108	5/11/26	7:30 PM	5/13/26	7:33 PM
7556285	Class 106	5/11/26	7:34 PM	5/13/26	7:38 PM
7556288	Class 102	5/11/26	7:38 PM	5/13/26	7:40 PM
7556289	Class 102 (Dup)	5/11/26	7:38 PM	5/13/26	7:40 PM
7556291	Aux Gym (Dup)	5/11/26	8:07 PM	5/13/26	8:10 PM
7556286	Aux Gym	5/11/26	8:07 PM	5/13/26	8:10 PM
7556295	Aux Gym	5/11/26	8:20 PM	5/13/26	Missing
7556290	Aux Gym “Coach’s Office”	5/11/26	8:24 PM	5/13/26	8:28 PM
7556292	Aux Gym	5/11/26	8:27 PM	5/13/26	8:29 PM
7556297	Commons	5/11/26	8:30 PM	5/13/26	8:33 PM
7556302	Lecture Room	5/11/26	8:35 PM	5/13/26	8:39 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556296	Lecture Room	5/11/26	8:39 PM	5/13/26	8:42 PM
7556299	Lecture Room (Dup)	5/11/26	8:39 PM	5/13/26	8:42 PM
7556300	Dressing Room	5/11/26	8:51 PM	5/13/26	8:57 PM
7556248	Big Gym	5/11/26	8:58 PM	5/13/26	9:03 PM
7556301	Big Gym (Dup)	5/11/26	8:58 PM	5/13/26	9:03 PM
7556298	Big Gym	5/11/26	8:59 PM	5/13/26	Missing
7556303	A-3	5/11/26	9:07 PM	5/13/26	9:12 PM
7556294	Office A" Left"	5/11/26	9:11 PM	5/13/26	9:15 PM
7556304	Office B "Right"	5/11/26	9:14 PM	5/13/26	9:17 PM
7556403	Percussion	5/11/26	8:47 PM	5/13/26	9:18 PM
7556402	Big Gym	5/11/26	8:55 PM	5/13/26	9:21 PM
7556401	Big Gym	5/11/26	8:59 PM	5/13/26	9:22 PM
7556293	A1	5/11/26	9:14 PM	5/13/26	9:27 PM
7556247	A1 Dup	5/11/26	9:14 PM	5/13/26	9:27 PM
7556337	Attendance Office	5/11/26	3:46 PM	5/13/26	3:53 PM
7556334	Main Office	5/11/26	3:52 PM	5/13/26	3:57 PM
7556338	Principal	5/11/26	3:57 PM	5/13/26	4:02 PM
7556333	04 "Safe" Storage Room	5/11/26	3:53 PM	5/13/26	4:04 PM
7556330	Workroom	5/11/26	3:59 PM	5/13/26	4:09 PM
7556332	Activities Director	5/11/26	4:03 PM	5/13/26	4:12 PM
7556339	Assistant Principal	5/11/26	4:06 PM	5/13/26	4:15 PM
7556340	Process Coordinator	5/11/26	4:09 PM	5/13/26	4:19 PM
7556345	Assistant Principal	5/11/26	4:12 PM	5/13/26	4:20 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556346	Assistant Principal	5/11/26	4:13 PM	5/13/26	4:21 PM
7556347	90-Bandroom	5/11/26	4:20 PM	5/13/26	4:22 PM
7556351	90-Bandroom (Dup.)	5/11/26	4:20PM	5/13/26	4:22 PM
7556352	Office C-Nurses Station	5/11/26	4:36 PM	5/13/26	4:39 PM
7556348	Office A-Counselors	5/11/26	4:41 PM	5/13/26	4:43 PM
7556353	Office B-Social Worker	5/11/26	4:39 PM	5/13/26	4:40 PM
7556354	Office G-Glenn	5/11/26	4:44 PM	5/13/26	4:47 PM
7556355	Office F-Nimmo	5/11/26	4:47 PM	5/13/26	4:49 PM
7556356	Office E-Bentley	5/11/26	4:51 PM	5/13/26	4:52 PM
7556357	Class 301	5/11/26	4:54 PM	5/13/26	4:56 PM
7556358	Class 303	5/11/26	4:58 PM	5/13/26	5:00 PM
7556359	Class 305	5/11/26	5:04 PM	5/13/26	5:05 PM
7556360	Class 304	5/11/26	5:07 PM	5/13/26	5:10 PM
7556363	Class 306	5/11/26	5:09 PM	5/13/26	5:12 PM
7556361	Class 308	5/11/26	5:12 PM	5/13/26	5:15 PM
7556362	Class 308 (Dup)	5/11/26	5:12 PM	5/13/26	5:15 PM
7556364	Class 307	5/11/26	5:16 PM	5/13/26	5:20 PM
7556366	Class 310	5/11/26	5:20 PM	5/13/26	5:25 PM
7556371	Class 309	5/11/26	5:22 PM	5/13/26	5:27 PM
7556365	Class 135	5/11/26	5:26 PM	5/13/26	5:29 PM
7556367	Class 133 A	5/11/26	6:07 PM	5/13/26	6:10 PM
7556368	Class 133 B	5/11/26	6:11 PM	5/13/26	6:14 PM
7556370	Class 134	5/11/26	6:13 PM	5/13/26	6:15 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556369	Class 132	5/11/26	6:16 PM	5/13/26	6:19 PM
7556373	Class 130	5/11/26	6:19 PM	5/13/26	6:23 PM
7556372	Class 130 (Dup)	5/11/26	6:19 PM	5/13/26	6:27 PM
7556374	Class 129	5/11/26	6:22 PM	5/13/26	6:29 PM
7556375	Class 127	5/11/26	6:45 PM	5/13/26	6:47 PM
7556379	Class 126	5/11/26	6:33 PM	5/13/26	6:36 PM
7556381	Class 124	5/11/26	6:37 PM	5/13/26	6:40 PM
7556382	Woodshop	5/11/26	6:40 PM	5/13/26	6:43 PM
7556376	Workshop A Office	5/11/26	6:43 PM	5/13/26	6:47 PM
7556377	Class 122	5/11/26	7:00 PM	5/13/26	7:02 PM
7556378	Class 122 A	5/11/26	7:04 PM	5/13/26	7:06 PM
7556380	Class 120	5/11/26	7:08 PM	5/13/26	7:11 PM
7556383	Class 121	5/11/26	7:10 PM	5/13/26	7:14 PM
7556384	Class 119	5/11/26	7:13 PM	5/13/26	7:16 PM
7556385	Class 119 (Dup)	5/11/26	7:13 PM	5/13/26	7:16 PM
7556386	Class 118	5/11/26	7:16 PM	5/13/26	7:20 PM
7556387	Class 115	5/11/26	7:18 PM	5/13/26	7:24 PM
7556388	Class 116	5/11/26	7:36 PM	5/13/26	7:40 PM
7556389	Class 114	5/11/26	7:38 PM	5/13/26	7:43 PM
7556390	Class 113	5/11/26	7:42 PM	5/13/26	7:45 PM
7556391	90 Office	5/11/26	8:11 PM	5/13/26	8:12 PM
7556395	Weight Room	5/11/26	8:17 PM	5/13/26	8:20 PM
7556396	Aerobics Room	5/11/26	8:20 PM	5/13/26	8:22 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556392	Class 83	5/11/26	8:28 PM	5/13/26	8:31 PM
7556393	Class 83 (Dup)	5/11/26	8:28 PM	5/13/26	8:31 PM
7556397	Office	5/11/26	8:32 PM	5/13/26	8:35 PM
7556394	Music Library	5/11/26	8:34 PM	5/13/26	8:36 PM
7556398	Guard Closet	5/11/26	8:37 PM	5/13/26	8:39 PM
7556399	Mud Room	5/11/26	8:40 PM	5/13/26	8:42 PM
7556400	Practice Room	5/11/26	8:44 PM	5/13/26	8:47 PM
7556404	A2	5/11/26	8:46 PM	5/13/26	8:48 PM
7556323	104	5/11/26	8:50 PM	5/13/26	Missing
7556324	100’s Hallway	5/11/26	8:55 PM	5/13/26	Missing
7556321	100’s Hallway	5/11/26	8:58 PM	5/13/26	Missing
7556309	100’s Hallway	5/11/26	9:02 PM	5/13/26	9:04 PM
7556307	Fitness Hallway	5/11/26	9:05 PM	5/13/26	9:07 PM
7556316	Room 12	5/11/26	9:08 PM	5/13/26	9:10 PM
7556306	Break Room/Copy Room	5/11/26	9:11 PM	5/13/26	9:12 PM
7556315	Process Coordinator	5/11/26	9:15 PM	5/13/26	9:18 PM
7556308	Spirit Store	5/11/26	9:18 PM	5/13/26	9:20 PM
7556349	A13 (LB)	5/11/26	4:00 PM	5/13/26	4:05 PM
7556341	A13 (LB)	5/11/26	4:00 PM	5/13/26	4:05 PM
7556336	A13 (LB)	5/11/26	4:00 PM	5/13/26	4:05 PM
7556331	A14 (OB)	5/11/26	4:07 PM	5/13/26	9:22 PM
7556350	A14 (OB)	5/11/26	4:07 PM	5/13/26	9:22 PM
7556343	A14 (OB)	5/11/26	4:07 PM	5/13/26	9:22 PM

SAMPLE #	LOCATION	DATE STARTED	TIME STARTED	DATE COLLECTED	TIME COLLECTED
7556342	A15 (FB)	5/11/26	4:00 PM	5/13/26	9:23 PM
7556335	A15 (FB)	5/11/26	4:00 PM	5/13/26	9:23 PM
7556344	A15 (FB)	5/11/26	4:00 PM	5/13/26	9:23 PM

ADDITIONAL REMARKS:

Please email results to: paule@titankc.com,
kgranger@titankc.com

Sampled by: Karla Granger
PRINTED Name

TURNAROUND TIME: Standard



SIGNATURE

CUSTODY

Relinquished By:  Date/Time: 5/14/26 @1800

Received By: _____ Date/Time: _____

PLEASE RETURN ORIGINAL COPY TO TITAN ENVIRONMENTAL SERVICES, INC.

P.O. Box 410295, Kansas City, Missouri 64141 Phone (913) 432-5500 : Fax (913) 432-0704

May 15, 2026 **** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
1411 S. RIDGEVIEW DR., WARRENSBURG, MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7556333	04 â SAFEâ STORAGE ROOM	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.5 ± 0.3	2026-05-15
7556309	100'S HALLWAY	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556269	200â S HALLWAY	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.5 ± 0.3	2026-05-15
7556272	300â S HALLWAY	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.6 ± 0.3	2026-05-15
7556271	400â S HALLWAY	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.7 ± 0.3	2026-05-15
7556391	90 OFFICE	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	1.0 ± 0.3	2026-05-15
7556347	90-BANDROOM	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.8 ± 0.3	2026-05-15
7556351	90-BANDROOM (DUP.)	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.8 ± 0.3	2026-05-15
7556253	94A	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.8 ± 0.3	2026-05-15
7556303	A-3	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556293	A1	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	0.5 ± 0.3	2026-05-15
7556247	A1 DUP	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556341	A13 (LB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556336	A13 (LB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556349	A13 (LB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556331	A14 (OB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556350	A14 (OB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556343	A14 (OB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556342	A15 (FB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556344	A15 (FB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556335	A15 (FB)	2026-05-11 @ 4:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556404	A2	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556332	ACTIVITIES DIRECTOR	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556396	AEROBICS ROOM	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.6 ± 0.3	2026-05-15
7556339	ASSISTANT PRINCIPAL	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.6 ± 0.3	2026-05-15
7556346	ASSISTANT PRINCIPAL	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.7 ± 0.3	2026-05-15
7556345	ASSISTANT PRINCIPAL	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.9 ± 0.3	2026-05-15
7556337	ATTENDANCE OFFICE	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.6 ± 0.3	2026-05-15
7556286	AUX GYM	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	< 0.3	2026-05-15
7556275	AUX GYM	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.6 ± 0.3	2026-05-15
7556292	AUX GYM	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.6 ± 0.3	2026-05-15
7556291	AUX GYM (DUP)	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.6 ± 0.3	2026-05-15
7556290	AUX GYM â COACHâ S OFFICEâ	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.9 ± 0.3	2026-05-15
7556401	BIG GYM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.3 ± 0.3	2026-05-15
7556402	BIG GYM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.1 ± 0.3	2026-05-15
7556248	BIG GYM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.0 ± 0.3	2026-05-15
7556301	BIG GYM (DUP)	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

May 15, 2026

** LABORATORY ANALYSIS REPORT **

Radon test result report for:

1411 S. RIDGEVIEW DR., WARRENSBURG, MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7556243	BREAK ROOM	2026-05-11 @ 4:00 pm	2026-05-13 @ 5:00 pm	0.8 ± 0.3	2026-05-15
7556306	BREAK ROOM/COPY ROOM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556257	CLASS 100	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.0 ± 0.3	2026-05-15
7556251	CLASS 101	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	1.1 ± 0.3	2026-05-15
7556252	CLASS 101 B	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.9 ± 0.3	2026-05-15
7556288	CLASS 102	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.9 ± 0.3	2026-05-15
7556289	CLASS 102 (DUP)	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	1.0 ± 0.3	2026-05-15
7556279	CLASS 105	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.1 ± 0.3	2026-05-15
7556285	CLASS 106	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.8 ± 0.3	2026-05-15
7556281	CLASS 107	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.1 ± 0.3	2026-05-15
7556287	CLASS 108	2026-05-11 @ 7:00 pm	2026-05-13 @ 8:00 pm	0.7 ± 0.3	2026-05-15
7556282	CLASS 110	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.7 ± 0.3	2026-05-15
7556283	CLASS 112	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.9 ± 0.3	2026-05-15
7556284	CLASS 112 â OFFICEâ	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556390	CLASS 113	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.8 ± 0.3	2026-05-15
7556389	CLASS 114	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	1.1 ± 0.3	2026-05-15
7556387	CLASS 115	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.9 ± 0.3	2026-05-15
7556388	CLASS 116	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	1.3 ± 0.3	2026-05-15
7556386	CLASS 118	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.9 ± 0.3	2026-05-15
7556384	CLASS 119	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.9 ± 0.3	2026-05-15
7556385	CLASS 119 (DUP)	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.8 ± 0.3	2026-05-15
7556380	CLASS 120	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556383	CLASS 121	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556377	CLASS 122	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556378	CLASS 122 A	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.8 ± 0.3	2026-05-15
7556381	CLASS 124	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556379	CLASS 126	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.6 ± 0.3	2026-05-15
7556375	CLASS 127	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.9 ± 0.3	2026-05-15
7556374	CLASS 129	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.1 ± 0.3	2026-05-15
7556373	CLASS 130	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.0 ± 0.3	2026-05-15
7556372	CLASS 130 (DUP)	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.0 ± 0.3	2026-05-15
7556369	CLASS 132	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.1 ± 0.3	2026-05-15
7556367	CLASS 133 A	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.1 ± 0.3	2026-05-15
7556368	CLASS 133 B	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.9 ± 0.3	2026-05-15
7556370	CLASS 134	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	1.1 ± 0.3	2026-05-15
7556365	CLASS 135	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	1.0 ± 0.3	2026-05-15
7556249	CLASS 137	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	1.2 ± 0.3	2026-05-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

May 15, 2026

** LABORATORY ANALYSIS REPORT **

Radon test result report for:

1411 S. RIDGEVIEW DR., WARRENSBURG, MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7556250	CLASS 139	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	1.2 ± 0.3	2026-05-15
7556241	CLASS 202	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	1.0 ± 0.3	2026-05-15
7556238	CLASS 203	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556234	CLASS 204	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	1.0 ± 0.3	2026-05-15
7556232	CLASS 205	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556233	CLASS 206	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.6 ± 0.3	2026-05-15
7556237	CLASS 207	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556236	CLASS 208	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.5 ± 0.3	2026-05-15
7556230	CLASS 209	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556231	CLASS 210	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556235	CLASS 210 (DUP)	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.6 ± 0.3	2026-05-15
7556357	CLASS 301	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556274	CLASS 303	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	< 0.3	2026-05-15
7556358	CLASS 303	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556360	CLASS 304	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556359	CLASS 305	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.5 ± 0.3	2026-05-15
7556363	CLASS 306	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556364	CLASS 307	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556361	CLASS 308	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556362	CLASS 308 (DUP)	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.7 ± 0.3	2026-05-15
7556371	CLASS 309	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556366	CLASS 310	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	< 0.3	2026-05-15
7556265	CLASS 402	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.9 ± 0.3	2026-05-15
7556267	CLASS 403	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.9 ± 0.3	2026-05-15
7556266	CLASS 403 (DUP)	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.7 ± 0.3	2026-05-15
7556268	CLASS 404	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	< 0.3	2026-05-15
7556273	CLASS 405	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.8 ± 0.3	2026-05-15
7556262	CLASS 406	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.7 ± 0.3	2026-05-15
7556258	CLASS 80	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	< 0.3	2026-05-15
7556255	CLASS 81	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	< 0.3	2026-05-15
7556263	CLASS 82	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	< 0.3	2026-05-15
7556264	CLASS 82 (DUP)	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.7 ± 0.3	2026-05-15
7556392	CLASS 83	2026-05-11 @ 8:00 pm	2026-05-13 @ 9:00 pm	1.8 ± 0.3	2026-05-15
7556393	CLASS 83 (DUP)	2026-05-11 @ 8:00 pm	2026-05-13 @ 9:00 pm	1.8 ± 0.3	2026-05-15
7556260	CLASS 91	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.6 ± 0.3	2026-05-15
7556245	CLASS 92	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.7 ± 0.3	2026-05-15
7556246	CLASS 93	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.8 ± 0.3	2026-05-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

May 15, 2026

** LABORATORY ANALYSIS REPORT **

Radon test result report for:

1411 S. RIDGEVIEW DR., WARRENSBURG, MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7556259	CLASS 94	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.6 ± 0.3	2026-05-15
7556297	COMMONS	2026-05-11 @ 8:00 pm	2026-05-13 @ 9:00 pm	0.6 ± 0.3	2026-05-15
7556244	COMMONS BY SHOP	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.7 ± 0.3	2026-05-15
7556239	COMMONS BY SHOP (DUP)	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	1.0 ± 0.3	2026-05-15
7556242	COMMONS SE CORNER	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.9 ± 0.3	2026-05-15
7556240	COMMONS WEST CORNER	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.7 ± 0.3	2026-05-15
7556300	DRESSING ROOM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	0.7 ± 0.3	2026-05-15
7556307	FITNESS HALLWAY	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556398	GUARD CLOSET	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.4 ± 0.3	2026-05-15
7556280	L20	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556302	LECTURE ROOM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	0.8 ± 0.3	2026-05-15
7556296	LECTURE ROOM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	0.8 ± 0.3	2026-05-15
7556299	LECTURE ROOM (DUP)	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	0.6 ± 0.3	2026-05-15
7556256	LIBRARY	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.8 ± 0.3	2026-05-15
7556276	LIBRARY â LION ROOMâ	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.1 ± 0.3	2026-05-15
7556277	LIBRARY B ROOM	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.4 ± 0.3	2026-05-15
7556270	LIBRARY TABLE AREA	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	0.7 ± 0.3	2026-05-15
7556278	LIBRARY TABLE AREA (DUP)	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556261	LITTLE THEATRE	2026-05-11 @ 6:00 pm	2026-05-13 @ 6:00 pm	0.7 ± 0.3	2026-05-15
7556334	MAIN OFFICE	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.8 ± 0.3	2026-05-15
7556399	MUD ROOM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.8 ± 0.3	2026-05-15
7556394	MUSIC LIBRARY	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.9 ± 0.3	2026-05-15
7556397	OFFICE	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	2.9 ± 0.3	2026-05-15
7556348	OFFICE A-COUNSELORS	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.6 ± 0.3	2026-05-15
7556294	OFFICE Aâ LEFTâ	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556304	OFFICE B â RIGHTâ	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556353	OFFICE B-SOCIAL WORKER	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.5 ± 0.3	2026-05-15
7556352	OFFICE C-NURSES STATION	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.7 ± 0.3	2026-05-15
7556356	OFFICE E-BENTLEY	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.6 ± 0.3	2026-05-15
7556355	OFFICE F-NIMMO	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.7 ± 0.3	2026-05-15
7556354	OFFICE G-GLENN	2026-05-11 @ 5:00 pm	2026-05-13 @ 5:00 pm	0.6 ± 0.3	2026-05-15
7556403	PERCUSSION	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.5 ± 0.3	2026-05-15
7556400	PRACTICE ROOM	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	1.5 ± 0.3	2026-05-15
7556338	PRINCIPAL	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	< 0.3	2026-05-15
7556315	PROCESS COORDINATOR	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556340	PROCESS COORDINATOR	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.6 ± 0.3	2026-05-15
7556316	ROOM 12	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

May 15, 2026

** LABORATORY ANALYSIS REPORT **

Radon test result report for:

1411 S. RIDGEVIEW DR., WARRENSBURG, MAIN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7556308	SPIRIT STORE	2026-05-11 @ 9:00 pm	2026-05-13 @ 9:00 pm	< 0.3	2026-05-15
7556395	WEIGHT ROOM	2026-05-11 @ 8:00 pm	2026-05-13 @ 8:00 pm	0.9 ± 0.3	2026-05-15
7556382	WOODSHOP	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.0 ± 0.3	2026-05-15
7556330	WORKROOM	2026-05-11 @ 4:00 pm	2026-05-13 @ 4:00 pm	0.7 ± 0.3	2026-05-15
7556376	WORKSHOP A OFFICE	2026-05-11 @ 7:00 pm	2026-05-13 @ 7:00 pm	1.1 ± 0.3	2026-05-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Your health risk

The primary health risk from long-term exposure to radon is lung cancer. The risk of developing a lung cancer from radon exposure depends both on how much radon is present and how long you are exposed to radon. The higher the radon level or the longer the time of exposure, even if the levels are relatively low, the greater the risk. Exposures up to 4 pCi/L may present some risk of contracting lung cancer to more sensitive occupants, especially children and those who live with smokers. The US Congress set as a goal the lowering of radon levels in buildings to equal the levels of outside air.

PERFORMING RADON TESTS FOR A REAL ESTATE TRANSACTION

US EPA protocols state that when using passive devices, such as activated charcoal tests, two short-term tests should be conducted, either together or sequentially, at the same location in the building. The tests should be averaged together and if the average is 4.0 pCi/L or higher, radon mitigation is recommended. Even if the average is below 4.0 pCi/L, the buyers should consider testing in a different season or deploy a long-term test device to assess their long-term risks. It is **highly recommended** that any property transaction tests be conducted by a non-interested third party. To locate a listed or certified radon tester, contact your state radon office or visit our website at http://www.neha-nrpp.org to download a list of NEHA-NRPP certified testers. You should also visit the EPA website to download a copy of EPA's Home Buyer's and Seller's Guide to Radon.

Radon Test Device Placement

The US EPA recommends that testing device(s) be placed in the lowest level of the home that could be used regularly, whether it is finished or unfinished. Conduct the test in any space that could be used by the buyer as a bedroom, play area, family room, den, exercise room, or workshop. Based on their client's intended use of the space, the qualified testing professional should identify the appropriate test location and inform their client (buyer). Do not test in a closet, stairway, hallway, crawl space or in an enclosed area of high humidity or high air velocity. An enclosed area may include a kitchen, bathroom, laundry room or furnace room.

Variations in Radon Levels

When tests are performed in different seasons or under different weather conditions, the initial screening and follow-up tests may vary considerably. Radon levels can vary significantly between seasons, so different values **are to be expected**. Even during normal weather, indoor radon levels may rise and fall by a factor of two on a daily cycle; for example, from 5 pCi/L to 10 pCi/L in 24 hours. During rapidly changing or stormy weather, the levels may change more dramatically. Because continual changes in radon levels are considered normal, expose the testing device for as long as is practical, while following the manufacturer's recommendations. This, of course, provides a better overall average of the measurement.

If you are comparing tests, or are averaging a series of tests, bear in mind that any radon test returns only the average of the levels present during a **specific period of time** at the **precise location** of the test. Conditions during a different test period or at a different location in the building are **expected to be different.**

Test results can also vary if the radon test instructions were not carefully followed. A laboratory measuring radon in samples taken outside the lab **must rely on the person conducting the test**. For example, the wrong starting or ending date of a test will significantly affect the calculated result. The location of each radon test can also influence the result. For example, a test placed in the blowing air stream of a fan is likely to collect more radon than it would under normal conditions. Also, three tests conducted in one home, but in three different rooms, **would be expected to have at least slightly different test results.**

Test results from a properly used activated charcoal test will more closely reflect the average radon concentrations over the last three to four days of the test period. This happens because the radon collected by the activated charcoal has a radioactive half-life of only four days. Thus, much of the radon collected early in a seven day test has already begun to decay prior to the conclusion of the test.

Retesting

It is important to understand that radon levels can change at some point in the future. Therefore, it is important to retest when there is occupancy by a new owner, before and after a new addition to the house, alterations that could alter ventilation patterns, if major cracks are noticed in foundation walls or the slab, you begin using a ground contact area of the home not previously tested, or even recent nearby construction blasting or earthquakes. EPA recommends that homes be retested every 2-3 years. If the home has been previously mitigated or alterations are made to the mitigation system, retesting should be done.

Mitigation


When radon mitigation is necessary, it is advisable that a state-licensed or nationally- certified contractor be used to design and install the mitigation system. For easy to read mitigation information, go to the US EPA website and download a copy of the Consumer's Guide to Radon Reduction.

For technical information, call (828) 684-0893. Office hours are Mon-Fri 8:30 to 5:30 EASTERN
You can reach us by Fax at (828) 684-8498 or write to Air Chek, Inc., Box 2000, Naples, NC 28760
Web Site: http://www.radon.com **Email to:** info@radon.com

APPENDIX B – USEPA & STATE OF MISSOURI RADON ZONE MAPS

Radon Zones Map

The U.S. Environmental Protection Agency (EPA) created this map to identify areas with the potential for elevated indoor radon levels. The EPA Map of Radon Zones helps national, state, and local organizations implement radon-resistant building codes. The map should not be used to determine if a home in a given zone should be tested for radon. Homes with elevated levels of radon have been found in all three zones. All homes should be tested for radon.



What do the colors mean?

	Zone 1 (red zones)	Highest potential; average indoor radon levels may be greater than 4 pCi/L (picocuries per liter)
	Zone 2 (orange zones)	Moderate potential; average indoor radon levels may be between 2 and 4 pCi/L
	Zone 3 (yellow zones)	Low potential; average indoor radon levels may be less than 2 pCi/L


MISSOURI - EPA Map of Radon Zones

http://www.epa.gov/radon/zonemap.html

The purpose of this map is to assist National, State and local organizations to target their resources and to implement radon-resistant building codes.

This map is not intended to determine if a home in a given zone should be tested for radon. Homes with elevated levels of radon have been found in all three zones.


All homes should be tested, regardless of zone designation.



IMPORTANT: Consult the publication entitled "Preliminary Geologic Radon Potential Assessment of Missouri" (USGS Open-file Report 93-292-G) before using this map. http://energy.cr.usgs.gov/radon/grpinfo.html This document contains information on radon potential variations within counties. EPA also recommends that this map be supplemented with any available local data in order to further understand and predict the radon potential of a specific area.

Zone 1 Zone 2 Zone 3

Average Radon Level in Tested Homes



Average by County

- < 2.0 pCi/L
- 2.0 - 3.9 pCi/L
- >= 4.0 pCi/L
- < 30 homes tested



*Source: Bureau of Environmental Epidemiology
Indoor Air Quality Database 2005 - 2015

APPENDIX C – SITE PHOTOGRAPHS & DRAWINGS



4
STORAGE
209
210
210


210
NOTICE
NO CELL PHONES
208
207
205



206
7556233
204
203
202








137




101A
PREP ROOM
101B
CHEMICAL STORAGE
94


93
7556260


91
95
MMXIX
80
81


82
402
University of Findlay
403
404


406
405
303


7556272
307
Mrs. Bergm
309
7556277


L20
IDEA LAB
Makerspace


Wild
VERY
ADOLESCENT
EARNER
107
112
OFFICE



110
108
106


7556288




7556290
M Oct
M 2027








LECTURE ROOM




A-3




MAIN OFFICE
7556334
USE BY
M Oct
K 2027


USE ONLY BLUE OR BLACK INK
NAME
TEST ADDRESS
TEST STATE
TEST ZIP
EMAIL ADDRESS OR CELL PHONE NUMBER
START DATE
START TIME
AM
PM
REMINDER:
NOON IS
12:00 PM
END TIME
END DATE
ROOM TEMP. +/- 6°F
FLOOR TESTED:
BASEMENT
1ST
2ND
OTHER:
ROOM TESTED:
CRAWLSPACE VENTS OPEN?
YES
NO
CLOSED HOUSE CONDITIONS?
TESTING FOR:
INITIAL
FOLLOW UP
REAL ESTATE
POST-MITIGATION
7556337
USE BY
W Oct
T 2027


Attendance
MAY NOT SPEAK
THE MANAGER
7556337
USE BY
W Oct
T 2027


7556334
12
1
2
3
4
5
6
7
8
9
10
11
Sterling & Noble


3
PRINCIPAL
WELCOME!
7556338
USE BY
Y Oct
W 2027


7556338


5
WORKROOM
7556330
USE BY
J Oct
Y 2027

7556330


6
ACTIVITIES DIR.
USE BY
X Oct
H 2027
7556332

7556332
PRINTED BY
Oct
2021


7
ASST. PRINCIPAL
WELCOME
7556339



OUR MISSION
OUR VALUES




8
PROCESS COORD.
WELCOME!
7556340



7556340
Valid By
Oct
2027


9
ASST. PRINCIPAL
7556345
Oct
2027



7556345
USE BY
Oct
2027
OUR MISSIO
The WHS Professional Learning
students for their
Relationships
We create and foster meaningful relationships among students, families, teachers, staff, and community partners


7556351


90
7556351
USE BY
Oct
2027



90
7556347
USE BY
C Oct
W 2027
COMMITMENT


7556346
USE BY
Oct
2027



ea Is
hone
e
cell
ngers.
use cell
in this area.
Please
keep
or
locked!
ASSISTANT PRINCIPAL S
OFFICE
Stephanie Colvin
2010
2011
Krysta Coggin
Michelle Fitzgerald
2012
Jamie Jackson
Erica Nowlin
2012
Katherine Turnbow
Alyssa Fox
WELCOME!
FRED B. HOUSE
AWARD OF MERIT
1990
JENNIFER BROWN
RANDY FRANK
1988
LORI BRYANT
TRAVIS BOETTCHER
1989
KIMBERLEY BROWN
BRENT GALPIN
7556346
USE BY
J Oct
T 2027
START DATE
START TIME
BND DATE
BND TIME
REMINDER:
NOON IS
12:00 PM
ROOM TEMP +/- 5°F
FLOOR TESTED:
BASEMENT
1ST
2ND
OTHER
ROOM TESTED:
CLOSED HOUSE CONDITIONS?
TEST STATE
TEST ZIP
NAME
TEST ADDRESS
EMAIL ADDRESS OR CELL PHONE NUMBER


Office
7556348
Use By
H Oct
X 2027


To:
Nurse
Lindsay
WE
LOV
FOUR
20/70
20/50
20/40
7556352


TIGERS
HEALTH
Nurse's Office
USE BY
7556352
C Oct
K 2027

7556347
USE BY
C Oct
W 2027


your effort
what you
believe
things
ou can
ontro
w kind
you are


HAPPY
Brenda Pennington
Social Worker
USE BY
7556353
Oct
2027

7556348
USE BY
Oct
2027
live SIM
DREAM
BE

BE KIND
YOU GET THIS
7556348
USE BY
H Oct
X 2027

Glen Gillogly Counselor

Mr. Gillogly


In My School Counseling Era



Favorites:
Season - Spring
Drink - Big Red
Color - Silver
Snack - Peanut M&Ms
Team/Sport - Chiefs
Holiday - Thanksgiving
Subject in HS - Math
Place visited - Europe, Hawaii, Pacific Northwest
TV show - Friends
Way to relax after a long day - Watching a movie with friends or family
Inspirational Quote - Believe you can and you are halfway there!

Years in Education - 28
Years as a School Counselor - 10

WHS Counselor (H-N)




7556354
USE BY
Oct
2027


Safe Zone
Welcome Back!
Mrs. Nimmo
Kelly Nimmo
Counselor
INDEPENDENT
STUDY FORMS
KANSAS
JAYHAWKS
7556355
USE BY
W Oct
T 2027
COMMITMENT


7556355
USE BY
W Oct
T 2021


Cindy Bentley
COUNSELOR
Mrs. Bentley
7556356
USE BY
H Oct
W 2027

YOU GOT THIS


7556356


USE BY
Oct
2027


WARRENSBURG HIGH SCHOOL


WHS Pyramid of Interventi



301
7556357
USE BY
K Oct
X 2027


Success
10
Tips Top
USE BY
Oct
2021
7556357


303
"The Warrensburg R-VI School District
24-25
COMMITMENT
TEAM • INTEGRITY • GRIT • ENTHUSIASM • RESPECT
My Commitment to 1% Better. Every. Day.
I will improve communication
w/ all parents
which will improve my relationship
w/ our community
Brennan R. Conners
will graduate and succeed in
to be confident and successful in
"Any student who is in Warrensburg"
7556358
USE BY
R Oct
Y 2027
TEST STATE
TEST ADDRESS
NAME
FIRST NAME
MIDDLE INITIAL
LAST NAME
SUFFIX
STREET NUMBER
STREET NAME
APT. NUMBER
CITY
STATE
ZIP CODE
BIRTH DATE
GENDER
ETHNICITY
GRADE
SCHOOL
TEACHER
CLASS
STUDENT ID
ENROLLMENT
REMINDER:
NOON IS
12:00 PM
START DATE
END DATE
ROOM TIMER: 45 MIN
FLOOR TESTED:
ROOM TESTED:
TESTING FOR:
INITIAL
PRETEST OF
POST ESTATE
OTHER
ASBESTOS
SAMPLE NUMBERS OR GRID PICNIC MARKER
USE ONLY BLUE OR BLACK INK


7556358
USE BY
R Oct
Y 2027


SCHOOLS
Dear Mrs English
Thank you for not giving up on me! I know it can be difficult sometimes. Thank you so much for your patience. I appreciate your good teaching, and I have learned so much this year. Have a good summer! God bless you.
From Kingston Newberry
Dear Mrs. English
Thank you for teaching me, and helping me learn through a topic matter that I struggle with.
From Luke Myers
Mrs. English's
RED
1 Algebra 1
2 Algebra A
3 PLAN
4 Algebra 1
WHITE
1 Algebra A
2 PLAN
3 Geometry
4 Algebra 1
306
Mrs. English is rea
The Demon of Unr
by Erik Larso
THE ART of WAR
JANE EYRE
7556363
USE BY
W Oct
R 2027


WHILE YOU
WERE OUT
Multipurpose Copy Paper
7556360
USE BY
Oct
2027

English's Schedule

	WHITE
1	Algebra A
2	PLAN
3	Geometry
4	Algebra 1

306


Mrs. Main's Schedule

	Red Days		White Days
R1	Plan	W1	Algebra 1
R2	Algebra A	W2	Algebra 1
R3	Algebra 1	W3	Plan
R4	Algebra A	W4	Geometry

304

g. English is reading:

The Demon of Unrest by Erik Larson



Mrs. Main is Reading. . .

JENNIFER ENGLISH

UCM


UNIVERSITY OF CENTRAL MISSOURI




7556359


USE BY
Oct
2027



Mrs.
Plymell
305
USE BY
Y Oct
C 2027
7556359



7556363
W Oct
R 2027
USE BY



308
7556361
USE BY
Oct
2027
7556362
USE BY
Oct
2027



7556361
USE BY
Oct
2027
RADON TEST
IN PROGRESS



TEST
GRESS
NOT
TURB
BUILDING
NS REQUIRED
7556362
USE BY
Oct
2027


MRS. DOWNS' SCHEDULE
RED DAY
1 Plan
2 ELA 1
3 ELA 1
4 Career English (Fall) Horror Lit (Spring)
WHITE DAY
1 ELA 1
2 Plan
3 ELA 1
4 ELA 1
307
Mrs. Downs is
7556364
USE BY
R Oct
T 2027



7556371
C
M
USE BY
Oct
2027



Mrs. Bergman
B.A. English Literature and Theory
William Jewell College
309
MRS. BERGMAN
IS READING
Theo of
Golden
Allen Levi
DEAR Mrs. Bergman
THANK YOU FOR ALL YOUR HARD WORK AND DEDICATION AND THANK YOU FOR DOING YOUR BEST FOR STUDENTS. PLEASE KNOW EVERYTHING YOU DO IS APPRECIATED AND EVERYTHING YOU ARE DOING IS MAKING A GOOD DIFFERENCE IN STUDENTS LIVES. THANK YOU MRS BERGMAN.
FROM KIERSTON NEWBERRY
DEAR Ms. Bergman
LOVE THE WAY YOU TEACH AND THANK YOU FOR HELPING ME!!!
FROM
7556371
USE BY
C Oct
M 2027


7556366
USE BY
X Oct
X 2027



Dear Matthew Basinger
I have enjoyed watching my son grow a love for history this year. Your unique way of connecting with students is inspiring! Keep being awesome.
From Jessica Smith
Dear Mr. Basinger, Mr. Sanchez
You guys have made history so fun, and stress free. I look forward to every red day because I know I won't have any homework in that class. You guys make the assignments fun and I like how you guys will give us class time in the next class if we don't finish our work.
From Reese Adams
Dear Mr. Sanchez
Thanks for teaching us, We'll miss you! <3
From Anthony Cleveroger
310
7556366
USE BY
X Oct
X 2027



SS ROOM
THURSDAYS ROOM 135
33a
135
7556365
USE BY
Y Oct
W 2027


COPY PAPER
7556365
Oct
2027
USE BY
ACCESS
DENIED
MAKE NEW
FRIENDS


Mr. Reuter is
THE CIASSROOM
133a
USE BY
Oct
2027
7556367


7556367
USE-BY
T
Y
Oct
2027


ABANDON ALL HOPE
YE WHO ENTER HERE
132
Like
7556369
J Oct
H 2027


7556370
USE BY
W Oct
K 2027
JOIN THE LEGACY
2025-2026
$525.00

134

7556370

USE BY
W Oct
K 2027

TEST ADDRESS

TEST STATE

EMAIL ADDRESS OR CELL PHONE NUMBER

START DATE 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21

START TIME (1) (2) (3) (4) (5) (6) (AM) REMINDER: NOON IS 12:00 PM END TIME
(7) (8) (9) (10) (11) (12) (PM)

END DATE 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21


ROOM TEMP +/- 5°F (40) (45) (50) (55) (60) (65) (70) (75) (80) CRAWLSPACE YES


FLOOR TESTED: ☐ BASEMENT ☐ 1ST ☐ 2ND ☐ OTHER: _____

ROOM TESTED: _____ CLOSED HOUSE CONDITIONS?

TESTING FOR: ☐ INITIAL ☐ FOLLOW UP ☐ REAL ESTATE ☐ POST


7550368
M
C
Oct
2027


133b
7556368
USE BY
M Oct
C 2027



129
7556374


USE BY
CLOSED BUILDING
CONSTRUCTIONS REQUIRED


7556373

Use BY
Oct
2027

CLOSED
CONDITIONS RE


130
7556372
USE BY
Y Oct
R 2027
7556373


BIRCH
SAFE SPACE
Be the REASON Someone SMILES TODAY
7556369
USE BY
J Oct
H 2027



HESTIA ↔ VESTA
HADES ↔ PLUTO
LITERATURE
LITERATURE



126
7556379
TEST STATE
TEST ZIP
EMAIL ADDRESS OR CELL PHONE NUMBER
START DATE
REMINDER:
NOON IS
12:00 PM
SEND TIME
AM
PM
START TIME
SEND DATE
ROOM TEMP +/- 5°F
FLOOR TESTED:
BASEMENT
1ST
2ND
OTHER:
CRAWLSPACE VENTS OPEN?
YES
NO
ROOM TESTED:
CLOSED HOUSE CONDITIONS?
YES
NO
TESTING FOR:
INITIAL
FOLLOW UP
REAL ESTATE
POST-MITIGATION


7556379
K
J
001
2027






124
7556381
USE BY
Oct
2027
W
R



Greek Gods and Goddesses
1556375
USE BY
R Oct
X 2027


Western
127
7556375
USE BY
R Oct
X 2027
Emerson


USE BY
M Oct
Y 2027
7556376
USE ONLY BLUE OR BLACK INK
NAME
TEST ADDRESS
TEST STATE
EMAIL ADDRESS OR CELL PHONE
START DATE
START TIME
REMINDER:
NOON IS
12:00 PM
END DATE
ROOM TEMP +/- 5°F
FLOOR TESTED
BASEMENT
1ST
2ND
ROOM TESTED
TESTING FOR
INITIAL
FOLLOW UP



BALDOR
7556382



BINDERS
7556381
Technology
Mechanical Drawing



USE BY
H Oct 2027
M
7556380
USE ONLY BLUE OR BLACK INK
NAME
TEST ADDRESS
TEST ZIP
TEST STATE
EMAIL ADDRESS OR CELL PHONE NUMBER
START DATE
START TIME
END DATE
END TIME
REMINDER: NOON IS 12:00 PM
AM
PM
ROOM TEMP. 41-97
FLOOR TESTED:
BASEMENT
1ST
2ND
ROOM TESTED:
INITIAL
FOLLOW-UP
TESTING FOR:
CRAWLSPACE VENTS OPEN?
YES
NO
OTHER:
CLOSED HOUSE CONDITIONS?
YES
NO
REAL ESTATE
PROFESSIONAL





7856378



7556377
USE BY
Oct
2027


OFFICE
USE BY
7556378
2027


118
7556386
USE BY
K Oct
C 2027
NAME
TEST ADDRESS
TEST STATE
TEST ZIP
EMAIL ADDRESS OR CELL PHONE NUMBER
START DATE
SIGNATURE
REMINDER:
NOON IS
12:00 PM
END TIME
AM
PM
ROOM TESTED:
FLOOR TESTED:
BASEMENT
LIST
2ND
CRAWLSPA
TESTING FOR:
INITIAL
CLOSED HOUSE CO



7556385
7556384
Zone!
Please put all CELL PHONES headphones earbuds etc. away in your backpacks
Thank you



UCM
UNIVERSITY OF
CENTRAL MISSOURI
Mrs. Duane is Reading
Lord of
Chaos
119
7556385
USE BY
X Oct
Y 2027
7556384
USE BY
Y Oct
X 2027



7556383
USE BY
Oct
2027


WELCOME!
121
7556383



116
7556388
USE BY
Oct
2027
TEST STATE
TEST ADDRESS
EMAIL ADDRESS OR CELL P
REMINDER:
HOOH IS
12:00 PM
AM
PM
Thanks


7556387
USE BY
Oct
2027


115
7556387
USE BY
M Oct
H 2027
NAME
TEST ADDRESS
TEST STATE
EMAIL ADDRESS OR CELL PHONE NUMBER
REMINDER:
NOON IS
12:00 PM
START DATE
START TIME
AM
PM
RND DATE
ROOM TEMP +/- 5°F
FLOOR TESTED:
BASEMENT
1ST
2ND
OTHER:
CRAWLSPACE
ROOM TESTED:
TESTING FOR:
RADON
FOLLOW UP
RADON EXPERTS


7556386


7556388
Oct
2027


114
7556389
USE BY
T Oct
K 2027
TEST STATE

7556389

Oct
2027

EMAIL ADDRESS OR CELL PHONE NUMBER

TEST ZIP

TEST STATE


DANIEL COYLE
113
USE BY
T Oct
R 2027
7556390

7556390

USE BY
Oct
2027

EMAIL ADDRESS OR CELL PHONE NUMBER

TEST STATE

TEST ZIP

REMINDER
NOON IS
12:00 PM

START TIME

END TIME

START DATE

END DATE

ROOM TEMP. ± 4°F

ROOM TESTED

FLOOR TESTED

ROOM TOO HOT

TESTING PERIOD

CLASSES HOUSE CONDITIONS?

OTHER

OTHER SPACE VENTS OVER

YES

NO

PERMANENT

BASEMENT

2ND

1ST

ALT


PROBLEMS

YES

NO


7556395
M Oct
C 2027
USE BY


Weight Room
7556395


7556391
USE BY
H Oct
T 2027
NAME
TEST ADDRESS
TEST ZIP
TEST STATE
EMAIL ADDRESS OR CELL PHONE NUMBER
REMINDER:
NOON IS
12:00 PM
END TIME
CHEAP SPACE VENTS OPEN?
OTHER
2ND
CLOSED HOUSE COUNTRYSIDE?
REAL ESTATE
FOLLOW UP
HMTMA
BASEMENT
HST
LOOSE TESTER
HOUSE TESTER
TOWING FOR
YES
NO
POS-E-MITIGATION
SPACE TIME
2ND DATE
HOUSE TESTER + PT
Scholar
pleased to present
Foundation, Inc.


OFFICE
USE BY
H Oct
T 2027
7556391

104

7556391

USE BY
H Oct
T 2027

USE ONLY BLUE OR BLACK INK

TEST ADDRESS

TEST STATE

EMAIL ADDRESS OR CELL PH

STREET DATE 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 1

STREET TIME 1 2 3 4 5 6 AM
7 8 9 10 11 12 PM

REMINDER:
NOON IS
12:00 PM

END DATE 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17


ROOM TEMP. +/- 5°F 40 45 50 55 60 65 70 75 80 CRAW

FLOOR TESTED: ☐ BASEMENT ☐ 1ST ☐ 2ND ☐ OTHE

ROOM TESTED: _____

TESTING FOR: ☐ INITIAL ☐ FOLLOW UP ☐ REAL ESTATE

CLOSED HOUSE CONDI


Band Office
UCM
USE BY
7556397
Y Oct
J 2027


CONDITIONS
CASIO


UCM
UNIVERSITY OF
CENTRAL MISSOURI
83
7556392
7556393
USE BY
Oct.
2027

7556396

USE BY
Oct
2027

H R

TEST STATE

TEST TIP

TEST PROCESS

EMAIL ADDRESS OR CELL PHONE NUMBER

REMINDER:
NOON IS
12:00 PM

END TIME

SPRAY DATE

SPRAY TIME

2ND DATE

ROOM TEMP +/- 5°F

ROOM TESTED

FLOOR TESTED

BASEMENT

INITIAL

FOLLOW UP

1ST

2ND

CLOSED WOUND COMPLIMENT

REAL SENSOR

OTHER

CHARCOAL SMOKE VENTS OPEN?


YES

NO

NOT APPLICABLE


YES


NO



Aerobics Room
7556396
USE BY
R Oct
H 2027


7556398



GUARD CLOSET
7556398
USE BY
W Oct
K 2027


7556394
USE BY
Oct
2027



MUSIC LIBRARY
7556394
USE BY
Oct
2027


Hbi™
230 NE
Gist
1112
17349C
00U 0
NO COLOR UNDERWEAR
UNW
XL
0 5
7/6 DZ
90 EA
PutUp 000
906345730
FROM 90
OFFLO12
79153
7556397
Y
Oct
2027
USE BY


MUD ROOM
USE BY
2027
7556399


EXIT


7556399
M X Oct
2027
EXIT



PRACTICE ROOM
7556400



PERCUSSION CLOSET
ROW-LOFF.
tapspace
creativity in percussion
Fender
www.fender.com
SABIAN
BECAUSE SOUND MATTERS
drums dw
The Drummer's Choice
U.S.A. VF
THE DRUMMER'S CHOICE
mp
7556403



7556401
R Oct
X 2027
BASEBALL



NHS
E SECTION
7556402
Oct
2021


GARED
WWW.GAREDSPORTS.COM
HARRISONVILLE
WILDCATS
WILDCATS
7556402
USE BY
X Oct
Y 2027
GUEST
FOULS


80
7556404
M Oct
2027


7556403


BELIEVE
FFA
THE CREED
THE THREE CIRCLES
LEARNING TO DO
DOING TO LEARN
EARNING TO LIVE
LIVING TO SERVE
THE FFA MISSION
FFA ANIMAL



A-2
7556404
USE BY
M Oct
H 2027


You put camouflage on anything and it automatically becomes cool.


A-1
7556247
7556293



WHS
STUDENT SECTION
EXIT
7556401
R
X
Oct
2027
USE BY
BASEBALL

WARRENSBURG HIGH SCHOOL



Updated:
06-18-25

WARRENSBURG HIGH SCHOOL



Office 1

1 - Nyulassie, K
Smith, J.

SRO-Fischer, L

2- Hall, T
Woods, J..
3- Cahill, K.
4- Storage
5- Workroom
6- Duvall, J.
7- Lovercamp, A.
8- Guengerich, J.
9- Harmon, N.
10- Breakroom
11- Whitney, C.
12- Conference Room

Office 2

A-Stinson, J.
B-Pennington, B.
C-Jewell, L.
Stoll, R.
D-Breakroom
E-Bentley, C.
F-Nimmo, K.
G-Gillogly, G.

VO-AG BUILDING

SHOP

OFFICE

A2 Collins, D.

A1 Jennings, L.

A4

LOWER LEVEL

WRESTLING ROOM

Training Room

WOOD SHOP

122 Brandt, J.
120 Wiseman, M.
118 Cameron, C.
116 Obsuszt, M.
114 Snell, K.
124 Mowery, T..
126
128
130
83
132 Fowler, J.
134 Bushmeyer, A.
121 Hutchins, C.
119 Duane, S.
RR RR
115 Loerschler, T.
113 Grammer, C.
127 Binder, A.
129 Conklin, A.
Serv Rm
LIBRARY MEDIA CENTER
Miller, K.
107 Bergman, D.
105
110 Kearfott, M.
108 Ellis, Todd
106 Hunter, A.
104 Hutchens, J.
102
100 Pax, M.
80 Kuck, M.
Custodial
81 Smith, E.
82 Lawson, K.
133A Reuter, E.
133B Video Prod Lab
LibB
101 Science Lab Combs, C
135 Hatfield, V.
137 Giangrosso, P.
139
RR RR
Storage
Coach Office
PE Girls
PE Boys
GYM
Cavanah, C.
Hinnah, K.
Westphal, K.
Messinger, R.
Commons
Auditorium
Brigman, M
92
Smith, S.
91
Helms, K.
90 Ray, C.
96 Multi-Purpose
KITCHEN
Story, D..
Tchr Lounge
12
Office2
Office1

UPPER GYM

Aerobics
Storage
Weight Room

East2
202
204
206 Liebnitz, E.
208 Lewis, B.
210 Liebnitz, D.
203 Honan, A.
205 Ortiz-Ford, J.
207 Garcia, K.
209 Richner, D.
310 Basinger, M.
304 Main, A.
306 English J,
308 Inks, C.
307 Downs, T.
309 Bergman, A.
301 Solon, Z.
303 Cicon, B
305
305 Plymell, C.

LOWER LEVEL

402
401 Cicon, M.
403
Reed, A.
404
Bushmeyer, G.
406 Messinger, R
405 Samborski, J.
Burnard, E

Rm 139
Hill, Patrick
Ingram, M.
Solon, Z.
Thomas, C.

Updated:
06-18-25

(6) Dups.

APPENDIX D – TES PERSONNEL CERTIFICATIONS

Karla Granger

Has satisfactorily fulfilled the requirements set forth by the
National Radon Proficiency Program and is therefore certified as a:

Radon Measurement Professional

with Standard Services

NRPP ID 107404-RMP
Issued On: 2026-01-12 Expires: 2028-01-31

Valid for specific activities or measurement devices, which can be verified with NRPP. State and local agencies may have additional requirements.

In witness Whereof,
I have subscribed my name as a
Representative of NRPP

Ashley Falco
Chair, Certification Council