


Laboratory Report

CLIENT: Northern Adirondack CS
PROJECT: PWS 0902616, PbCu

WORK ORDER: 2509-32118
DATE RECEIVED: 9/16/25

001	Site: 7 ES Shop Sink				Date Sampled: 9/16/25		Time: 6:48	
Parameter	Result	Units	Method	Analysis Date/Time		Lab/Tech	NELAC	Qual.
Copper, Total	1.1	mg/L	EPA 200.8	9/30/25	19:48	W MGT	A	
Lead, Total	< 0.0010	mg/L	EPA 200.8	9/30/25	19:48	W MGT	A	
002	Site: 6 ES Teachers Room				Date Sampled: 9/16/25		Time: 6:45	
Parameter	Result	Units	Method	Analysis Date/Time		Lab/Tech	NELAC	Qual.
Copper, Total	1.1	mg/L	EPA 200.8	9/30/25	19:54	W MGT	A	
Lead, Total	0.0028	mg/L	EPA 200.8	9/30/25	19:54	W MGT	A	
003	Site: 10 ES Classroom 148				Date Sampled: 9/16/25		Time: 7:00	
Parameter	Result	Units	Method	Analysis Date/Time		Lab/Tech	NELAC	Qual.
Copper, Total	0.84	mg/L	EPA 200.8	9/30/25	20:05	W MGT	A	
Lead, Total	< 0.0010	mg/L	EPA 200.8	9/30/25	20:05	W MGT	A	
004	Site: 9 ES Nurses Office				Date Sampled: 9/16/25		Time: 6:50	
Parameter	Result	Units	Method	Analysis Date/Time		Lab/Tech	NELAC	Qual.
Copper, Total	0.74	mg/L	EPA 200.8	9/30/25	20:07	W MGT	A	
Lead, Total	0.0016	mg/L	EPA 200.8	9/30/25	20:07	W MGT	A	
005	Site: 8 ES Kitchen Sink				Date Sampled: 9/16/25		Time: 6:50	
Parameter	Result	Units	Method	Analysis Date/Time		Lab/Tech	NELAC	Qual.
Copper, Total	0.56	mg/L	EPA 200.8	9/30/25	20:09	W MGT	A	
Lead, Total	< 0.0010	mg/L	EPA 200.8	9/30/25	20:09	W MGT	A	

Test results comply with all NELAC requirements unless otherwise noted. This Laboratory Report includes the client's COC sample documentation and shall not be reproduced except in full, without written approval of the laboratory.



ENDYNE Inc.

www.endynelabs.com

Laboratory Report

CLIENT: Northern Adirondack CS
PROJECT: PWS 0902616, PbCux5

WORK ORDER: 2509-32173
DATE RECEIVED: 9/16/25

001	Site: 2 HW Teachers Lounge			Date Sampled: 9/16/25		Time: 6:15	
<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Method</u>	<u>Analysis Date/Time</u>	<u>Lab/Tech</u>	<u>NELAC</u>	<u>Qual.</u>
Copper, Total	0.83	mg/L	EPA 200.8	9/30/25 20:11	W MGT	A	
Lead, Total	0.0013	mg/L	EPA 200.8	9/30/25 20:11	W MGT	A	
002	Site: 4 HS Kitchen Sink			Date Sampled: 9/16/25		Time: 6:30	
<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Method</u>	<u>Analysis Date/Time</u>	<u>Lab/Tech</u>	<u>NELAC</u>	<u>Qual.</u>
Copper, Total	0.73	mg/L	EPA 200.8	9/30/25 20:13	W MGT	A	
Lead, Total	0.0031	mg/L	EPA 200.8	9/30/25 20:13	W MGT	A	
003	Site: 5 HS Shop - Maint Sink			Date Sampled: 9/16/25		Time: 6:40	
<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Method</u>	<u>Analysis Date/Time</u>	<u>Lab/Tech</u>	<u>NELAC</u>	<u>Qual.</u>
Copper, Total	0.17	mg/L	EPA 200.8	9/30/25 20:15	W MGT	A	
Lead, Total	< 0.0010	mg/L	EPA 200.8	9/30/25 20:15	W MGT	A	
004	Site: 1 HS Chemistry Lab			Date Sampled: 9/16/25		Time: 6:17	
<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Method</u>	<u>Analysis Date/Time</u>	<u>Lab/Tech</u>	<u>NELAC</u>	<u>Qual.</u>
Copper, Total	0.64	mg/L	EPA 200.8	9/30/25 20:17	W MGT	A	
Lead, Total	0.0026	mg/L	EPA 200.8	9/30/25 20:17	W MGT	A	
005	Site: 3 HS Nurses Office Sink			Date Sampled: 9/16/25		Time: 6:20	
<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Method</u>	<u>Analysis Date/Time</u>	<u>Lab/Tech</u>	<u>NELAC</u>	<u>Qual.</u>
Copper, Total	0.86	mg/L	EPA 200.8	9/30/25 20:26	W MGT	A	
Lead, Total	0.0045	mg/L	EPA 200.8	9/30/25 20:26	W MGT	A	

Test results comply with all NELAC requirements unless otherwise noted. This Laboratory Report includes the client's COC sample documentation and shall not be reproduced except in full, without written approval of the laboratory.