



Gantner- Gantner 2nd Floor gang bathroom plumbing




Gantner- 2nd floor ductwork installed




Gantner-Waterproofing



Gantner- Brick Work Continues



16th- Block fill applied




16th-Tie in wall constructed




16th-Remaining Windows installed



16th- Hallway Lighting Installed



Gilbert- Finish Paint



Gilbert- Shoring of tie in wall and new Beam installed



Gilbert- Lighting Fixtures in Hallway Installed



Gilbert- Additions Electrical tie in to existing buiding